U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT Sanford LPG Response - Removal Polrep Initial and Final Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region IV

Subject: POLREP #1

First and Final

Sanford LPG Response

Sanford, NC

Latitude: 35.4205455 Longitude: -79.1801569

To:

From: Kenneth Rhame, OSC

Date: 4/18/2011 **Reporting Period:** 4/17/2011

1. Introduction

1.1 Background

Site Number: Contract Number:

D.O. Number: Action Memo Date:

Response Authority: CERCLA Response Type: Emergency
Response Lead: PRP Incident Category: Removal Action

NPL Status: Non NPL Operable Unit:

 Mobilization Date:
 4/17/2011
 Start Date:
 4/17/2011

 Demob Date:
 4/17/2011
 Completion Date:
 4/17/2011

CERCLIS ID: RCRIS ID:

ERNS No.: State Notification: NC Emergency Management

FPN#: Reimbursable Account #:

1.1.1 Incident Category

Emergency Response Responded as Technical Support Asset Response was not conducted under CERCLA or OPA Authority

1.1.2 Site Description

Tobacco Farm

1.1.2.1 Location

446 Castleberry Road Sanford, NC

1.1.2.2 Description of Threat

Fire and Explosion

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

18,000 gallon Liquid Propane Gas (LPG) tank was damaged by tornado. A voluntary evacuation issued affecting 10 to 12 homes.

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

On 4/17/2011 EPA received a request for technical support from local fire relating to a 18,000 gallon liquid propane gas (LPG) tank that was damaged by a tornado. The LPG tank was damaged on 4/16.2011 by a tornado that picked the propane tank up off of its cradle and dropped it approx. 60 to 70 feet away from its original location. The valves and the vapor relief pipes were sheared off and ice had formed around the tank. The tank was located on Thomas Farm and was used to dry tobacco, according to the owner the tank had 9,000 gallons of LPG prior to the tornado. An estimated 6,000 gallons remained judging from the freeze line during the first entry conducted by Charlotte Haz-Mat. A voluntary evacuation was issued affecting approximately 10 to 12 homes.

Discussions were held to develop a strategy to possibly off-load the tank. Charlotte Haz-Mat made a second entry and noted that the freeze line had dropped 1 1/2 feet since the first entry and that the majority of the ice had thawed. Due to this observation it was decided by local fire, haz-mat, emergency management and epa that it would be best to allow the LPG to evaporate on its own while a team remains

on site to conduct air monitoring.

2.1.2 Response Actions to Date

EPA provided technical support.

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

No enforcement actions.

Potential Responsible Party is Steve Thomas, owner of Thomas Farm.

2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Manifest #	Treatment	Disposal

2.2 Planning Section

2.2.1 Anticipated Activities

Charlotte Haz-Mat will continue to monitor air and rate of LPG volatilization.

2.2.1.1 Planned Response Activities

Charlotte Haz-Mat will continue to conduct air monitoring to insure fire and explosion hazard is not created away from the exclusion zone.

2.2.1.2 Next Steps

EPA is on stand-by and will remobilize if situation worsens.

2.2.2 Issues

LPG is exempt from CERCLA Authority.

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

No information available at this time.

4. Personnel On Site

No information available at this time.

5. Definition of Terms

No information available at this time.

6. Additional sources of information

No information available at this time.

7. Situational Reference Materials

No information available at this time.