



Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 1

Date: 7/20/06

Direction: Northeast

Description: Final grade in parcel BCC-102



Photograph No. 2

Date: 7/20/06

Direction: North

Description: Backfilling and excavating activities in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 3

Date: 7/21/06

Direction: Northeast

Description: Stockpile of excavated soil to be treated.



Photograph No. 4

Date: 7/21/06

Direction: Northeast

Description: Excavation with stained soil in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 5

Date: 7/24/06

Direction: Southeast

Description: Excavation and shoring with stained soil near pool in BCC-103.



Photograph No. 6

Date: 7/26/06

Direction: East

Description: Stained soil in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 7

Date: 7/26/06

Direction: West

Description: Excavation and stained soil in BCC-103.



Photograph No. 8

Date: 7/26/06

Direction: South

Description: Scrape excavation of root mass with stained soil in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 9

Date: 7/28/06

Direction: Southeast

Description: Unknown pipe uncovered in BCC-103.



Photograph No. 10

Date: 7/28/06

Direction: Southeast

Description: Contaminated soil lens in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 11

Date: 7/28/06

Direction: West

Description: Utility lines uncovered near house in BCC-103.



Photograph No. 12

Date: 7/28/06

Direction: West

Description: Stained soil in root mass in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 13

Date: 7/28/06

Direction: Southeast

Description: Final grade in southwest portion of BCC-103.



Photograph No. 14

Date: 7/28/06

Direction: Southeast

Description: START collecting laboratory confirmation sample from BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 15

Date: 7/28/06

Direction: Southeast

Description: ERRS
conducting dust suppression in
BCC-103.



Photograph No. 16

Date: 7/29/06

Direction: Northwest

Description: Abandoned
telephone line in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 17

Date: 7/29/06

Direction: Southeast

Description: Septic system
leach field in BCC-103.



Photograph No. 18

Date: 7/29/06

Direction: Southeast

Description: ERRS
investigating septic system
prior to excavating near t.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 19

Date: 7/29/06

Direction: Northwest

Description: ERRS
uncovering septic line.



Photograph No. 20

Date: 7/29/06

Direction: Northwest

Description: Septic line
towards leachfield.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 21

Date: 7/31/06

Direction: West

Description: Excavating stained soil in BCC-103.



Photograph No. 22

Date: 7/31/06

Direction: Southwest

Description: Stained soil lens near house in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 23

Date: 7/31/06

Direction: Southwest

Description: ERRS
conducting dust suppression in
BCC-103.



Photograph No. 24

Date: 7/31/06

Direction: Southeast

Description: Excavated area
near septic tank in BCC-103.





Photographic Documentation

Client: U.S.E.P.A

Location: Barker Chemical, Inglis, FL

Photograph Date: July 20-31, 2006

Contract No.:

Prepared by: Tetra Tech EMI

Photographer: Billy Bol/Aaron Klug

Project Number: I9010E060030008

TDD No.:

Photograph No. 25

Date: 7/31/06

Direction: East

Description: Stained soil near root mat in BCC-103.



Photograph No. 26

Date: 7/31/06

Direction: Northwest

Description: Backfilled area in BCC-103.

