



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** Exterior, west side of Building 11. ACM pipe wrap at elevation along wall.
PHOTO NO: 1 **DIRECTION:** Southeast
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** ACM paper on floor in second-floor loft of Building 20.
PHOTO NO: 2 **DIRECTION:** Northeast
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** ACM pipe wrap on floor, northwest corner of second floor of Building 11
PHOTO NO: 3 **DIRECTION:** North
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** ACM in a base board seam of floor of the east and central rooms of the upstairs locker room in Building 2.
PHOTO NO: 4 **DIRECTION:** South
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter
PHOTO NO: 5
PHOTOGRAPHER: S. Meyer

DATE: December 7, 2004
DIRECTION: Northeast

SUBJECT: ACM pipe insulation on floor along the east wall of the east room of the upstairs locker room in Building 2.



SITE: Quincy Smelter
PHOTO NO: 6
PHOTOGRAPHER: S. Meyer

DATE: December 7, 2004
DIRECTION: Northeast

SUBJECT: ACM pipe wrap on floor and in drums in second floor loft of Building 2.



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** ACM insulation in crates at south end of second floor loft of Building 2.
PHOTO NO: 7 **DIRECTION:** East
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** ACM paper/heat shield on east wall of northwest room of Building 3.
PHOTO NO: 8 **DIRECTION:** East
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** ACM pipe wrap hanging in central area of
PHOTO NO: 9 **DIRECTION:** East basement of Building 3.
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 7, 2004 **SUBJECT:** ACM chimney chute insulation at the west
PHOTO NO: 10 **DIRECTION:** South side of Building 3.
PHOTOGRAPHER: S. Meyer




SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** Interior of the eastern shed attachment to Building 3; debris on floor. View from doorway.
PHOTO NO: 11 **DIRECTION:** Southwest
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** Roof conditions over northwest portion of Building 7; falling and missing panels are visible.
PHOTO NO: 12 **DIRECTION:** Up, Northeast
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe wrap at elevation along north exterior wall of Building 7.
PHOTO NO: 13 **DIRECTION:** Southwest
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe wrap at elevation along north exterior wall of Building 7; wrapped pipe running left to right through photo, and wrapped pipe stub above upper window.
PHOTO NO: 14 **DIRECTION:** South
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe wrap at elevation along south interior wall of Building 14, above man door.
PHOTO NO: 15 **DIRECTION:** Southwest
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe wrap at elevation along ceiling of Building 16.
PHOTO NO: 16 **DIRECTION:** Northwest
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM debris on floor of Building 16; many similar patches on floor throughout Building 16.
PHOTO NO: 17 **DIRECTION:** Down
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe wrap on floor at base of central, interior stack of Building 18; east side of stack.
PHOTO NO: 18 **DIRECTION:** West
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe and valve wrap along west wall of Building 17, north room.
PHOTO NO: 19 **DIRECTION:** North
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe wrap at elevation along south interior wall of the north room of Building 24.
PHOTO NO: 20 **DIRECTION:** Southeast
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 8, 2004 **SUBJECT:** ACM pipe wrap at elevation along north exterior wall of Building 24.
PHOTO NO: 21 **DIRECTION:** Southwest
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 9, 2004 **SUBJECT:** Several runs of ACM pipe wrap at elevation along south interior wall of Building 18.
PHOTO NO: 22 **DIRECTION:** Up, North
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 9, 2004 **SUBJECT:** ACM valve wrap on machine on the floor of the north room of Building 17.
PHOTO NO: 23 **DIRECTION:** East
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 9, 2004 **SUBJECT:** Several runs of ACM pipe wrap along south interior wall of the north room of Building 17.
PHOTO NO: 24 **DIRECTION:** South
PHOTOGRAPHER: S. Meyer



SITE: Quincy Smelter **DATE:** December 9, 2004
PHOTO NO: 25 **DIRECTION:** West
PHOTOGRAPHER: S. Meyer

SUBJECT: ACM pipe wrap on pipes along north wall of Building 18 and elevated wooden stack access platform surrounding interior smoke stack of Building 18.