

Incident 2350477
Kings Tire Recycler Facility Fire
ERT Photo Log (pm) 08/18/12











Photo of the retention pond from atop a windrow of chipped tires (facing east). The oil is daylighting along the southern wall of the pond with the majority of oil currently appearing at the southeastern corner of the pond.



Photo of oil collection/recovery activities along the eastern end of the retention pond.



Collection Point 2 at the rear of the facility structure. Water is orange in color with oil weeping from the southern wall of the pit.



Collection Point 2 at the rear of the facility structure.
Oil is weeping from the southern portion of the pit.



Photo from rear of property facing west toward the facility entrance. Structure remnants are to the left and the retention pond is to the right. The “berm” is actually tires that have been capped with soil.



Photo from rear of property facing west toward the facility entrance.
The trenched area was used for borrow material to extinguish the tire fire.



Collection Point 2 at the rear of the facility structure. Water is orange in color with oil weeping from the southern wall of the pit.





Photo of skimming operations at the eastern end of the retention pond. The retention pond runs east to west along the northern eastern portion of the property.