



Location: 1554

Priority: **Moderate**

Access: Easy

Notes: Dam of sticks and logs across 80% of surface collecting mousse covering surface area approximately 3ft x 10ft (watch out for large 24" snapping turtle seen in water). Access through junkyard road off Catawba Drive.

Photos: DSCN2663, DSCN2664, DSCN2665, DSCN2667



Location: 1603

Priority: **Low**

Access: Easy

Notes: Small area of mousse and debris caught. Access 100ft upstream from location 1554.

Photos: DSCN2670



Location: 1613

Priority: **Moderate**

Access: Easy

Notes: Mousse and debris trapped in brush over three spots. Covers area approximately 3ft x 5ft, 1ft x 5ft, and 3ft x 5ft. Near backyard of home. The sheen in this area is thicker. Access from backyard of home off Catawba Drive.

Photos: DSCN2671, DSCN2672, DSCN2673



Location: 1620

Priority: **Moderate**

Access: Moderate

Notes: Spots of mousse with debris trapped in brush and vegetation. Covers approximately 1ft x 3ft. Located approximately 200ft upstream of location 1613 (photos 2674-2675). Red material is bacteria NOT OIL in photos 2676-2677. Also heavy oiling approximately 50ft upstream of location 1620 (photos 2678-2680). Covers approximately 2ft x 8ft. Access is a walk 200-250ft upstream from backyard of home off Catawba Drive.

Photos: DSCN2674, DSCN2675, DSCN2676, DSCN2677, DSCN2678, DSCN2679, DSCN2680





Location: 1624

Priority: **Low**

Access: Difficult

Notes: Small spot of mousse and debris within brush. Access could be from backyard of house on Catawba drive or from sewer ROW

Photos: DSCN2681



Location: 1632

Priority: **High**

Access: Difficult

Notes: Heavy oiling with some oil, mixed with debris and vegetation. Covers area approximately 6ft x 10ft. Access would be approximately 250-300ft upstream from sewer ROW.

Photos: DSCN2682, DSCN2683, DSCN2684, DSCN2685, DSCN2686



Location: 1643

Priority: **Low**

Access: Difficult

Notes: Sporadic oiled debris caught in brush. Covers area approximately 1ft x 2ft. Access would be approximately >600ft upstream from sewer ROW.

Photos: DSCN2687



Location: 1648

Priority: **Moderate**

Access: Difficult

Notes: Large mat of mousse covers area approximately 3ft x 6ft with debris. Material will not easily float downstream. Access would be >700ft from either the sewer ROW or the power ROW.

Photos: DSCN2688



Location: 1651

Priority: **Moderate**

Access: Difficult

Notes: Large mat of mousse covers area approximately 4ft x 4ft with debris. Mousse appears to be fresher than material seen in downstream locations. Material will not easily float downstream. Access would be >400ft downstream from the power ROW.

Photos: DSCN2689, DSCN2690, DSCN2691, DSCN2692, DSCN2693



Location: 1657

Priority: **Low**

Access: Difficult

Notes: Light mousse collecting in area 1ft x 4ft on rocks in shallow water. Access would be 100ft downstream from the power ROW.

Photos: DSCN2694, DSCN2695



Location: 1707

Priority: **Low**

Access: Moderate

Notes: Light mousse collecting on rocks in shallow water covering area <1sqft. Access <100ft upstream from the power ROW.

Photos: DSCN2702



Location: 1712

Priority: **Low**

Access: Moderate

Notes: Pocket of fresh mousse without debris collecting in area 1ft x 3ft (photo 2703). Also 20ft upstream is area of light mousse with debris and oil on rocks in shallow water. Access 150 feet upstream from the power ROW.

Photos: DSCN2703, DSCN2704



upstream

Location: 1718

Priority: **Highest**

Access: Difficult

Notes: Dammed water surface with logs and brush collected oil and mousse in area in excess of 10ft x 20ft. Access in excess of 300ft upstream from power ROW.

Photos: DSCN2705, DSCN2706, DSCN2707, DSCN2709, DSCN2710



Location: 1721

Priority: **Highest**

Access: Difficult

Notes: Dammed water surface with logs and brush collected oil and mousse in area in excess of 8ft x 12ft. Located 50ft upstream from location 1718. Access in excess of 300ft upstream from power ROW.

Photos: DSCN2711



Location: 1728

Priority: **Low**

Access: Difficult

Notes: Pockets of mousse on rocks in shallow water. Four spots total each approximately 1sqft. Access difficult from either power ROW or highway.

Photos: DSCN2712, DSCN2713



Location: 1732

Priority: **Low**

Access: Difficult

Notes: Small pocket of light mousse in area approximately 1sqft on rocks. Access difficult from either power ROW or highway.

Photos: DSCN2715



Location: 1736

Priority: **Low**

Access: Moderate

Notes: Light mousse in brush covers area approximately 1ft x 3ft. May float away before recovery. Access <200ft downstream from boom and vac truck location at highway.

Photos: DSCN2716



Location: 1743

Priority: **Low**

Access: Easy

Notes: Oiled material and mousse on water surface and in culvert. Access from highway.

Photos: DSCN2719, DSCN2720



Location: 1757

Priority: **Low**

Access: Easy

Notes: Weathered mousse in sun covers approximately 1sqft. Easy access from Given Street.

Photos: DSCN2723



Location: 1800

Priority: **Low**

Access: Easy

Notes: Light mousse and stringing mousse along water surface at dam along residence with boom. Easy access from residence Given Street.

Photos: DSCN2724, DSCN2725, DSCN2726, DSCN2727

