

## Appendix C

### Photo Documentation



<b>Logbook Photo #</b>	DSC00600
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	11/13/13
<b>Time</b>	1012
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Public notice sign posted at the entrance of the Recycling facility for the duration of the clean-up activities.



<b>Logbook Photo #</b>	DSC00570
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	11/08/13
<b>Time</b>	1723
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of one sign posted around the excavation zones for the duration of the clean-up activities.



<b>Logbook Photo #</b>	DSC1010
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	1/28/14
<b>Time</b>	0750
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Loading of contaminated soil from Area A into disposal trucks. Dust suppression in progress.	




<b>Logbook Photo #</b>	DSC00827
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	1/8/14
<b>Time</b>	0911
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	<p>Loading of contaminated soil from Area B into disposal trucks. Dust suppression in progress.</p>



<b>Logbook Photo #</b>	DSC00598
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	Down
<b>Date</b>	11/13/13
<b>Time</b>	0908
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Contaminated soil loaded on disposal truck, "burrito-wrapped," proper labels attached, prior to leaving the site for disposal at a disposal facility.



<b>Logbook Photo #</b>	DSC00596
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	Down
<b>Date</b>	11/13/13
<b>Time</b>	0907
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Contaminated soil loaded on disposal truck, "burrito-wrapped," proper labels attached (see photo above), prior to leaving the site for disposal at a disposal facility.



<b>Logbook Photo #</b>	DSC00607
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	11/14/13
<b>Time</b>	1203
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Station 1: air sample and air monitor (see figures for location of Station 1).



<b>Logbook Photo #</b>	DSC00567
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	11/8/13
<b>Time</b>	1719
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
View of Station 2: air sample and air monitor (see figures for location of Station 2).	



<b>Logbook Photo #</b>	DSC00611
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	11/14/13
<b>Time</b>	1204
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Station 3: air sample (see figures for location of Station 3).




<b>Logbook Photo #</b>	DSC00613
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	11/14/13
<b>Time</b>	1217
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**

View of Station 4: air sample and air monitor Fibrous Aerosol Monitor (FAM-1). Note that the FAM-1 was situated between the nearest residence and the site. (see figures for location of Station 4).



<b>Logbook Photo #</b>	DSC00612
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	11/14/13
<b>Time</b>	1206
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Station 5: air monitor (see figures for location of Station 5).



<b>Logbook Photo #</b>	DSC00621
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	11/16/13
<b>Time</b>	0859
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Station 6: air sample (cassette hanging from the metal gate). (see figures for location of Station 6).



<b>Logbook Photo #</b>	DSC00622
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	11/16/13
<b>Time</b>	0902
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**


View of Station 7: air sample (cassette hanging from the pole in the middle of the picture). (see figures for location of Station 7).



<b>Logbook Photo #</b>	DSC00623
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	11/16/13
<b>Time</b>	0905
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Station 8: air sample and air monitor (see figures for location of Station 8).



<b>Logbook Photo #</b>	DSC00693
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	12/6/13
<b>Time</b>	1609
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
View of Station 9: air sample and air monitor (see figures for location of Station 9).	



<b>Logbook Photo #</b>	DSC00887
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	1/13/14
<b>Time</b>	1337
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**


View of Station 10: air sample and air monitor Fibrous Aerosol Monitor (FAM-1). Note that the FAM-1 was situated between the nearest residence and the site. (see figures for location of Station 10).



<b>Logbook Photo #</b>	DSC00819
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/7/14
<b>Time</b>	1529
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Station 11: air sample (see figures for location of Station 11).




<b>Logbook Photo #</b>	DSC00813
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/7/14
<b>Time</b>	1115
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
View of Station 12: air sample (see figures for location of Station 12).	



<b>Logbook Photo #</b>	DSC00886
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	1/13/14
<b>Time</b>	1536
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Station 13: air sample and air monitor (see figures for location of Station 13).



<b>Logbook Photo #</b>	DSC00713
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/9/13
<b>Time</b>	1138
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of indoor air sample station and co-located/duplicate sample inside the auxiliary warehouse at W. Silver Recycling facility.



<b>Logbook Photo #</b>	DSC00965
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	1/23/14
<b>Time</b>	1604
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Indoor air sampling at SWV W. Silver Recycling Trailer/Scale Office.



<b>Logbook Photo #</b>	DSC00550
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	West
<b>Date</b>	11/6/13
<b>Time</b>	1550
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Interior of Exfoliation building in advance of abatement.	



<b>Logbook Photo #</b>	DSC00603
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	East
<b>Date</b>	11/13/13
<b>Time</b>	1501
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Interior of Exfoliation building (2 <sup>nd</sup> floor) in advance of abatement.




<b>Logbook Photo #</b>	DSC00604
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	11/13/14
<b>Time</b>	1510
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Interior of Exfoliation building (2 <sup>nd</sup> floor) in advance of abatement.



<b>Logbook Photo #</b>	DSC00581
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	11/11/13
<b>Time</b>	1640
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Abatement contractor crew set-up during the abatement activities inside the Exfoliation building.



<b>Logbook Photo #</b>	DSC00583
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	11/11/13
<b>Time</b>	1537
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Abatement contractor crew set-up during the abatement activities inside the Exfoliation building.



<b>Logbook Photo #</b>	DSC00601
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	11/13/14
<b>Time</b>	1438
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Abatement contractor during the clean-up activities inside the Exfoliation building.



<b>Logbook Photo #</b>	DCS00585
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N/A
<b>Date</b>	11/11/14
<b>Time</b>	1538
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Abatement contractor during the clean-up activities inside the Exfoliation building.



<b>Logbook Photo #</b>	DSC00602
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	11/13/13
<b>Time</b>	1439
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Bags of contaminated material during the abatement activities inside the Exfoliation building.



<b>Logbook Photo #</b>	DSC00659
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	12/2/13
<b>Time</b>	0840
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
<p>Post-abatement photo inside the exfoliation building. Second floor loft of the west side of the exfoliation building.</p>	



<b>Logbook Photo #</b>	DSC00660
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/2/13
<b>Time</b>	0840
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Post-abatement photo inside the exfoliation building. Frist floor of the exfoliation building.



<b>Logbook Photo #</b>	DSC00661
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	12/2/14
<b>Time</b>	0841
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Post-abatement photo inside the exfoliation building. Frist floor of the exfoliation building.	



<b>Logbook Photo #</b>	DSC00664
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	12/2/13
<b>Time</b>	0841
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
<p>Post-abatement photo inside the exfoliation building. Room on the east side of the exfoliation building on the Frist floor</p>	



<b>Logbook Photo #</b>	DSC00689
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/6/13
<b>Time</b>	0945
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Dismantling side walls and roof for recycling, prior to the building demolition of the exfoliation building.



<b>Logbook Photo #</b>	DSC00692
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	12/6/13
<b>Time</b>	1417
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Dismantling side walls and roof for recycling, prior to the building demolition of the exfoliation building.



<b>Logbook Photo #</b>	DSC00695
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	12/7/13
<b>Time</b>	1326
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Building demolition of the exfoliation building. Dust suppression in progress.



<b>Logbook Photo #</b>	DSC00725
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	12/10/13
<b>Time</b>	1531
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Excavated and soil confirmation samples collected at grid (Area A, Grid-001), adjacent to and north of the former exfoliation building.	



<b>Logbook Photo #</b>	DSC00727
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	12/11/13
<b>Time</b>	0951
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
<p>Excavated and soil confirmation samples collected at grid (Area A, Grid-002), adjacent to and south of the former exfoliation building. <i>Note: this is only partial excavation and confirmation sample on Grid-002, see next photo for the remainder of Grid-002.</i></p>	




<b>Logbook Photo #</b>	DSC00752
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	12/14/13
<b>Time</b>	1036
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**

Excavated and soil confirmation samples collected at grid (Area A, Grid-002), adjacent to and south of the former exfoliation building. *Note: this is only partial excavation and confirmation sample on Grid-002, see previous photo for the remainder of Grid-002.*



<b>Logbook Photo #</b>	DSC00726
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	12/11/13
<b>Time</b>	0951
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavated and soil confirmation samples collected at grid (Area A, Grid-003), adjacent to and west of the former exfoliation building.



<b>Logbook Photo #</b>	DSC00823
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	1/8/14
<b>Time</b>	0810
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Concrete placed around the perimeter of the former exfoliation building, after the excavation and soil confirmation samples were collected. This is in preparation for the new warehouse to be built over the former exfoliation building. Picture shown is Area A, Grid-002.



<b>Logbook Photo #</b>	DSC00826
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	1/8/14
<b>Time</b>	0811
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**  
 Concrete placed around the perimeter of the former exfoliation building, after the excavation and soil confirmation samples were collected. This is in preparation for the new warehouse to be built over the former exfoliation building. Picture shown is Area A, Grid-003.



<b>Logbook Photo #</b>	DSC00753
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	12/16/13
<b>Time</b>	0845
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavation activities at Area A, Grid A – Southwest. Dust suppression in progress.



<b>Logbook Photo #</b>	DSC00754
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/16/13
<b>Time</b>	1002
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling (5-pt composite) after a two-foot removal at Area A, Grid A – Southwest.



<b>Logbook Photo #</b>	DSC00756
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	12/16/13
<b>Time</b>	1356
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfill activities at Area A, Grid A – Southwest after a two-foot removal.



<b>Logbook Photo #</b>	DSC001015
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	1/28/14
<b>Time</b>	1104
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**  
View of excavated area in the central portion of Area A, Grid A following collection of the soil confirmation sample.



<b>Logbook Photo #</b>	DSC01018
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	1/28/14
<b>Time</b>	1559
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Backfill activities in the excavated area in the central portion of Area A, Grid A following collection of the soil confirmation sample.	



<b>Logbook Photo #</b>	DSC00988
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/26/14
<b>Time</b>	1054
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavation and dust suppression activities in Area A, Grid A - North



<b>Logbook Photo #</b>	DSC00997
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	1/26/14
<b>Time</b>	1454
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfill activities at Area A, Grid A – North after excavation activities.




<b>Logbook Photo #</b>	DSC00758
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	12/17/13
<b>Time</b>	1209
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of excavated and confirmation sample on Area A, Grid-019 (partial sample). See next photo for the remaining section of Area A, Grid-019.



<b>Logbook Photo #</b>	DSC00759
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	12/17/13
<b>Time</b>	1214
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**  
View of excavated and confirmation sample on Area A, Grid-019 (partial sample). See previous photo for the remaining section of Area A, Grid-019.



<b>Logbook Photo #</b>	DSC00795
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	12/21/13
<b>Time</b>	1410
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfilled Area A, Grid-019 after excavation and confirmation sample collected. See next photo for the remaining section of Area A, Grid-019.



<b>Logbook Photo #</b>	DSC00794
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	12/21/13
<b>Time</b>	1410
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfilled Area A, Grid-019 after excavation and confirmation sample collected. See previous photo for the remaining section of Area A, Grid-019.



<b>Logbook Photo #</b>	DSC00575
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	11/9/13
<b>Time</b>	1310
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavation with dust suppression activities at Area A, Grid B – North.



<b>Logbook Photo #</b>	DSC00652
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	11/22/13
<b>Date</b>	S
<b>Time</b>	1438
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Backfilling and grading activities in Area A, Grid B – North.	



<b>Logbook Photo #</b>	DSC00677
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/4/13
<b>Time</b>	1117
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavation with dust suppression activities at Area A, Grid B – South.



<b>Logbook Photo #</b>	DSC00680
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/4/13
<b>Time</b>	1228
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation sample after a two-foot removal on Area A, Grid B – North.



<b>Logbook Photo #</b>	DSC00971
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/24/14
<b>Time</b>	1600
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling (5 pt composite) after a two-foot removal on Area A, Grid C – South.



<b>Logbook Photo #</b>	DSC00976
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/25/14
<b>Time</b>	0807
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Backfilling activities after a two-foot removal and confirmation soil sampling in Area A, Grid C – South.	



<b>Logbook Photo #</b>	DSC00979
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	1/25/14
<b>Time</b>	1500
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavation (24" bgs) and dust suppression activities in Area A, Grid C – North.



<b>Logbook Photo #</b>	DSC01000
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/26/14
<b>Time</b>	1608
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of Area A, Grid C backfilled and soil grading activities after a 24"bgs removal.




<b>Logbook Photo #</b>	DSC986
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	1/26/14
<b>Time</b>	1001
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Excavated Area A, Grid C - West	



<b>Logbook Photo #</b>	DSC0998
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	1/26/14
<b>Time</b>	1606
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfilled Area A, Grid C - West



<b>Logbook Photo #</b>	DSC00928
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/19/14
<b>Time</b>	1036
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling (5pt composite) after a 24"bgs removal on Area A, Grid D - East



<b>Logbook Photo #</b>	DSC00930
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	1/19/14
<b>Time</b>	1039
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling (5pt composite) after a 24"bgs removal on Area A, Grid D - Middle



<b>Logbook Photo #</b>	DSC00913
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/18/14
<b>Time</b>	0925
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavation and dust suppression activities in Area A, Grid D – West, including soil in the rail spur.



<b>Logbook Photo #</b>	DSC00933
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/19/14
<b>Time</b>	1134
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfill and soil grading activities on Area A, Grid D – West.



<b>Logbook Photo #</b>	DSC00934
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	1/19/14
<b>Time</b>	1446
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfill activities on Area A, Grid D – East and Middle.



<b>Logbook Photo #</b>	DSC00766
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/20/13
<b>Time</b>	0856
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**

Excavated Area A, Grid E and confirmation samples collected prior to backfill activities. Partial grid, see next photo for the remainder of Area A, Grid E.



<b>Logbook Photo #</b>	DSC00767
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/20/13
<b>Time</b>	0856
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Excavated Area A, Grid E and confirmation samples collected prior to backfill activities. Partial grid, see previous photo for the remainder of Area A, Grid E.	



<b>Logbook Photo #</b>	DSC00788
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/21/13
<b>Time</b>	1252
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	<p>Area A, Grid E backfilled after excavation and confirmation samples collected.            Partial grid, see next photo for the remainder of Area A, Grid E.</p>




<b>Logbook Photo #</b>	DSC00790
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	W
<b>Date</b>	12/21/13
<b>Time</b>	1253
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
<p>Area A, Grid E backfilled after excavation and confirmation samples collected.            Partial grid, see previous photo for the remainder of Area A, Grid E.</p>	



<b>Logbook Photo #</b>	DSC00816
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/7/14
<b>Time</b>	1338
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)

**Description:**  
 Excavation and dust suppression activities in Area B – NM DOT Rail Road Right-of-Way.



<b>Logbook Photo #</b>	DSC00821
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/7/14
<b>Time</b>	1529
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Excavation and dust suppression activities in Area B – NM DOT Rail Road Right-of-Way.	



<b>Logbook Photo #</b>	DSC00839
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	1/8/14
<b>Time</b>	1341
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling activities in Area B – NM DOT Rail Road Right-of-Way.



<b>Logbook Photo #</b>	DSC00843
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	1/8/14
<b>Time</b>	1351
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
View of a vein of possible vermiculite located along Area B, Grids 013 and 014, after excavation activities. The sample is in Area B – NM Rail Road Right-of-Way. A sample was sent to the lab for analysis.	



<b>Logbook Photo #</b>	DSC00845
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/8/14
<b>Time</b>	1445
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	View of a vein of possible vermiculite located along Area B, Grids 013 and 014, after excavation activities. The sample is in Area B – NM Rail Road Right-of-Way. A sample was sent to the lab for analysis.



<b>Logbook Photo #</b>	DSC00891
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	1/15/14
<b>Time</b>	1405
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
Area B – NMDOT Rail Road Right-of-Way backfilled after excavation and soil confirmation activities.	



<b>Logbook Photo #</b>	DC00673
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	12/3/13
<b>Time</b>	1444
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling (5-pt composite) after a two-foot removal on Area E, Grid 001 (City of Albuquerque, Right-of-Way).



<b>Logbook Photo #</b>	DSC00676
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	12/4/13
<b>Time</b>	0818
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfill activities after excavation and confirmation soil sampling on Area E, Grid 001 (City of Albuquerque, Right-of-Way).



<b>Logbook Photo #</b>	DSC00643
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	11/19/13
<b>Time</b>	1236
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling (5-pt composite) after a one-foot removal on Area E, Grid 002 (City of Albuquerque, Right-of-Way).




<b>Logbook Photo #</b>	DSC00645
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	11/20/13
<b>Time</b>	1556
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Area E, Grid 002 (City of Albuquerque, Right-of-Way) backfilled after excavation and confirmation soil sampling.



<b>Logbook Photo #</b>	DSC00647
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	11/21/13
<b>Time</b>	1122
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Confirmation soil sampling (5-pt composite) after a one-foot removal on Area E, Grid 006 (City of Albuquerque, Right-of-Way).



<b>Logbook Photo #</b>	DSC00649
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	11/21/13
<b>Time</b>	1252
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfill activities on Area E, Grid 006 (City of Albuquerque, Right-of-Way) after excavation and soil confirmation sampling.



<b>Logbook Photo #</b>	DSC00630
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	11/16/14
<b>Time</b>	1449
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Excavation activities on Area E, Grids 010 and 011 (City of Albuquerque, Right-of-Way). Dust suppression in progress.



<b>Logbook Photo #</b>	DSC00632
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	11/17/13
<b>Time</b>	1230
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Backfill activities after excavation and confirmation samples collected on Area E, Grids 010 and 011 (City of Albuquerque, Right-of-Way).



<b>Logbook Photo #</b>	DSC01103
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	2/10/14
<b>Time</b>	1452
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	D. Edgington (ERRS)
<b>Description:</b>	Abatement contractor set-up during the abatement clean-up inside the W. Silver Recycling warehouse.



<b>Logbook Photo #</b>	DSC01124
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	2/13/14
<b>Time</b>	1334
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	D. Edgington (ERRS)
<b>Description:</b>	Abatement contractor during the clean-up inside the W. Silver Recycling main warehouse.



<b>Logbook Photo #</b>	DSC01167
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	2/19/11
<b>Time</b>	1141
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	D. Edgington (ERRS)
<b>Description:</b>	
<p>White latex-type encapsulate ("AsbetoSafe" brand) was sprayed on the ceiling and walls after the pressure wash.</p>	



<b>Logbook Photo #</b>	DSC01209
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	2/25/14
<b>Time</b>	0954
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	D. Edgington (ERRS)
<b>Description:</b>	Asbestos abatement contractor continue to clean-up inside the W. Silver Recycling auxiliary warehouse.



<b>Logbook Photo #</b>	DSC01233
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	2/28/14
<b>Time</b>	1253
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	D. Edgington (ERRS)
<b>Description:</b>	
<p>White latex-type encapsulate ("AsbetoSafe" brand) was sprayed on the walls after the pressure wash in the auxiliary warehouse at W. Silver Recycling..</p>	



<b>Logbook Photo #</b>	DSC01050
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	2/1/14
<b>Time</b>	1359
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	D. Edgington (ERRS)
<b>Description:</b>	Abatement contractors conducting clean-up efforts inside the W. Silver Recycling Trailer/Scale Office.



<b>Logbook Photo #</b>	DSC01019
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/28/14
<b>Time</b>	1600
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	<p>An asbestos encapsulate was placed on the soil around/adjacent to the W. Silver scale and trailer.</p>




<b>Logbook Photo #</b>	DSC00978
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	1/25/14
<b>Time</b>	1145
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Power washing concrete pad between the W. Silver warehouse and the scrap yard area.



<b>Logbook Photo #</b>	DSC01006
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	1/27/14
<b>Time</b>	1340
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Mechanic shed area, located on the east side of the scrap yard area of W. Sliver Recycling, after the pressure wash.



<b>Logbook Photo #</b>	DSC04190
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N/A
<b>Date</b>	11/11/13
<b>Time</b>	1209
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N/A
<b>Description:</b>	
Backfill and crushed rocks source location in Albuquerque, NM	



<b>Logbook Photo #</b>	DSC00700
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/9/13
<b>Time</b>	0920
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	View of indoor dust sampling in SWV Main Office – Entry Wall (Sample SWVDust_MOD2).



<b>Logbook Photo #</b>	DSC00703
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/9/13
<b>Time</b>	0929
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	View of indoor dust sampling inside the SWV Main Office – Top of First Aid Kit (sample SWVDust_MOD3).



<b>Logbook Photo #</b>	DSC00705
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	Down
<b>Date</b>	12/9/13
<b>Time</b>	0938
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	
View of indoor dust sampling location in SWV Mail Office – Carpet Rug (SWVDust_MOD1)	



<b>Logbook Photo #</b>	DSC00706
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/9/13
<b>Time</b>	0945
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	View of indoor dust sampling in SWV PM Office - Electrical/Network Closet (East of office) (Sample No. SWVDust_POD1)



<b>Logbook Photo #</b>	DSC00708
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/9/13
<b>Time</b>	0952
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	View of indoor sampling at SWV PM Office - Window Sill (South) (Sample SWVDust_POD2).



<b>Logbook Photo #</b>	DSC00710
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	12/9/13
<b>Time</b>	0956
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	D N. Bischocho (START)
<b>Description:</b>	View of indoor dust sampling at SWV PM Office - Bookshelf (NW) (Sample SWVDust_POD3).



<b>Logbook Photo #</b>	DSC00769
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/20/13
<b>Time</b>	1134
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at SWV Main Warehouse (Window Sill - South) (Sample SWVDust_WARD01).



<b>Logbook Photo #</b>	DSC00771
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/20/13
<b>Time</b>	1140
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	
Indoor dust sampling at SWV Main Warehouse (Wall - South) (sample SWVDust_WARD02).	



<b>Logbook Photo #</b>	DSC00772
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	12/20/13
<b>Time</b>	1150
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	
Indoor dust sampling at SWV Main Warehouse (Wall - East) (Sample SWVDust_WARD03).	




<b>Logbook Photo #</b>	DSC00776
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	12/20/13
<b>Time</b>	1203
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at SWV Main Warehouse (Hopper Brace - North) (Samples SWVDust_WARD04 and Duplicate SWVDust_WARD40).



<b>Logbook Photo #</b>	DSC00778
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	12/20/13
<b>Time</b>	1212
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at SWV Auxillary Warehouse - West (Wall - North) (Sample SWV_WARD05).



<b>Logbook Photo #</b>	DSC00779
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	12/20/13
<b>Time</b>	1220
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	
Indoor dust sampling at SWV Auxillary Warehouse - West (Security Camera) (Sample SWVDust_WARD06).	




<b>Logbook Photo #</b>	DSC00781
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	12/20/13
<b>Time</b>	1225
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	
Indoor dust sampling at SWV Auxillary Warehouse - West (2nd Floor Vanity shelf) (Sample No. SWVDust)WARD07).	



<b>Logbook Photo #</b>	DSC00784
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	12/20/13
<b>Time</b>	1233
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at SWV Auxillary Warehouse - West (Work bench - SW) (Sample No. SWVDust_WARD08).




<b>Logbook Photo #</b>	DSC00870
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	1/11/14
<b>Time</b>	0938
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at SWV W. Silver Trailer Scale Office (Top of Refrigerator - South side of Office) (Sample Nos. SWVDust_WSTrail01 and Duplicate SWVDust_WSTrail10).



<b>Logbook Photo #</b>	DSC00873
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	1/11/14
<b>Time</b>	0951
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at SWV W. Silver Trailer Scale Office (Floor by south main entrance on the east side of the trailer) (Sample No. SWVDust_WSTrail02).



<b>Logbook Photo #</b>	DSC00875
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	E
<b>Date</b>	1/11/14
<b>Time</b>	0959
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor sampling at SWV W. Silver Trailer Scale Office (Bookshelf - Middle Part of trailer) (Sample No. SWVDust_WSTrail03).



<b>Logbook Photo #</b>	DSC00877
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NW
<b>Date</b>	1/11/14
<b>Time</b>	1005
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at SWV W. Silver Trailer Scale Office (Tools room - west of trailer) (Sample No. SWVDust_WSTrail04).



<b>Logbook Photo #</b>	DSC00717
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SE
<b>Date</b>	12/9/13
<b>Time</b>	1150
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	S. Cowan (START)
<b>Description:</b>	
View of bulk dust sampling inside W. Silver Recycling warehouse.	



<b>Logbook Photo #</b>	DSC00848
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	N
<b>Date</b>	1/9/14
<b>Time</b>	0926
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	
Bulk sampling (Impacted and unimpacted ceiling insulation) inside the W. Silver Recycling Main Warehouse (Samples SWV2_WARC01 and SWV2_WARC02).	



<b>Logbook Photo #</b>	DSC0882
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/11/14
<b>Time</b>	1030
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at EPA Field Office - Bookshelf by intake vent on EPA/START shared office - South side of trailer (SWVDust_EPATrail01).




<b>Logbook Photo #</b>	DSC00880
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	SW
<b>Date</b>	1/11/14
<b>Time</b>	1024
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	
Indoor dust sampling at EPA Field Office - Top of refrigerator (middle section of trailer) (SWVDust_EPATrail02).	



<b>Logbook Photo #</b>	DSC00879
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/11/14
<b>Time</b>	1018
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Indoor dust sampling at EPA Field Office - Bookshelf on ERRS office - North side of trailer (Sample SWVDust_EPATrail03).




<b>Logbook Photo #</b>	NB0004
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/16/14
<b>Time</b>	1800
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	
View into EPA Field Office Trailer as Decontamination is conducted.	



<b>Logbook Photo #</b>	DSC00961
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	S
<b>Date</b>	1/23/14
<b>Time</b>	1412
<b>Photographer</b>	N. Biscocho (START)
<b>Witness</b>	J. Koehnen (START)
<b>Description:</b>	Indoor air sampling at EPA Field Office Trailer.



<b>Logbook Photo #</b>	DSC00905
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/17/14
<b>Time</b>	1153
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	Decontamination set-up at EPA Field Office Trailer.



<b>Logbook Photo #</b>	DSC00906
<b>US EPA ID / Task Order Number</b>	CERCLIS: NMN000607041 / TDD No: 1/DYNAMAC-077-13-001
<b>Site</b>	Southwest Vermiculite (Removal 2)
<b>Location Address</b>	1800 1 <sup>st</sup> Street, NW
<b>City, State</b>	Albuquerque, New Mexico 87102
<b>County</b>	Bernalillo
<b>Direction/Orientation</b>	NE
<b>Date</b>	1/17/14
<b>Time</b>	1154
<b>Photographer</b>	J. Koehnen (START)
<b>Witness</b>	N. Biscocho (START)
<b>Description:</b>	View of ERRS conducting personal decontamination procedures prior to entering the EPA Field Office Trailer.