

Appendix E: Photographs, Zizzo Properties, Kenosha, WI



Photo 1: View inside conveyor tower



Photo 2: View south from tower area



Photo 3: View north from tower area



Photo 4: View NE toward debris pile on east side of property



Appendix E: Photographs, Zizzo Properties, Kenosha, WI



Photo 5: View inside red building on NW corner of property



Photo 6: View south from red building



Photos 7 & 8: Views east toward auto shredder fluff on east side of property



Appendix E: Photographs, Zizzo Properties, Kenosha, WI




Photo 9: View north from center of property




Photo 10: View south from center of property




Photo 11: View north from west edge of property.




Photo 12: Common ground surface appearance



Appendix E: Photographs, Zizzo Properties, Kenosha, WI




Photo 13: View north from south portion of site



Photo 14: View south in south portion of site



Photo 15: View inside building in south portion of site




Photo 16: View west along south edge of site



Appendix E: Photographs, Zizzo Properties, Kenosha, WI



Photo 17: View south from site




Photo 18; View southwest toward apartments above store



Photos 19: Auto fluff along east side of site



Photo 20: Drums on 2<sup>nd</sup> floor of tower

Appendix E: Photographs, Zizzo Properties, Kenosha, WI



Photo 21: View N from slightly east of site



Photo 22: Apartments SE of site



Photo 23: Debris and black soil beneath fence on west side of site



Photo 24: View to the west



Appendix E: Photographs, Zizzo Properties, Kenosha, WI



Photo 25: View east along north edge of site



Photo 26: View south from NW corner of site



Photo 27: View west from north portion of site



Photo 28: View north from north edge of site

Appendix E: Photographs, Zizzo Properties, Kenosha, WI



Photo 29: View southeast toward west side of property (note hole in fence)



Photo 30: Container of hydraulic oil in conveyor tower




Photo 31: View north from NE corner of the site toward 50<sup>th</sup> Street and access point to the site



Appendix E: Photographs, Zizzo Properties, Kenosha, WI



Photo 32: View east toward several fire extinguishers incorporated within auto shredder fluff



Photo 33: Stained soil near conveyor tower