

Broadway Hotel

Photo Category: Admin Record

Description: Debris pile of the former Broadway Hotel. Temporary fencing has been placed to deter trespassing but has been inadequate. Debris and friable asbestos containing materials are open to the air and environment. Facing east to showcase extent of debris pile.

Category: Admin Record Latitude: 40.5330641534572

Date Taken: 2/7/2022 Longitude: -112.28823258536

Tags:



Description: Debris pile of the former Broadway Hotel. Temporary fencing has been placed to deter trespassing but has been inadequate. Debris and friable asbestos containing materials are open to the air and environment. Facing northwest to showcase extent of debris pile.

Category: Admin Record Latitude: 40.5330322715873

Date Taken: 2/7/2022 Longitude: -112.288254042584

Tags:



Description: Debris pile of the former Broadway Hotel. Temporary fencing has been placed to deter trespassing but has been inadequate. Debris and friable asbestos containing materials are open to the air and environment. Facing north to showcase extent of debris pile and proximity to public walkways.

Category: Admin Record Latitude: 40.533048580645

Date Taken: 2/7/2022 Longitude: -112.288254042584

Tags:



Broadway Hotel

Photo Category: Admin Record

Description: Debris pile of the former Broadway Hotel. Temporary fencing has been placed to deter trespassing but has been inadequate. Debris and friable asbestos containing materials are open to the air and environment. Facing west to showcase extent of debris pile.

Category: Admin Record Latitude: 40.5330893532721

Date Taken: 2/7/2022 Longitude: -112.28823258536

Tags:



Description: Debris pile of the former Broadway Hotel. Temporary fencing has been placed to deter trespassing but has been inadequate. Debris and friable asbestos containing materials are open to the air and environment. Facing south to showcase extent of debris pile.

Category: Admin Record Latitude: 40.5330410300913

Date Taken: 2/7/2022 Longitude: -112.288254042584

Tags:

