



**Site:** Ohio Cast Products

**Photo Number:** 1

**Direction:** Northwest

**Subject:** Leaking aboveground fuel tank and waste oil drums in Area 8.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products


**Photo Number:** 2

**Direction:** Northwest

**Subject:** Leaking waste oil drums in Area 8.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 3

**Direction:** Down

**Subject:** Drum labeled methyl formate, flammable liquid in Area 5.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 4

**Direction:** West

**Subject:** Fire-damaged portion of the facility in Area 6.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 5

**Direction:** Southwest

**Subject:** Bagged solid material on pallets and spilled onto the floor in Area 5.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 6

**Direction:** North

**Subject:** Collection area of a soil sample (OCP-SS-052208-03) for VOCs in Area 5.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 7

**Direction:** Southeast

**Subject:** Outdoor Electrical substation on the south portion of the Site.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 8

**Direction:** South

**Subject:** Stained soil north of the transformer pad at the outdoor electrical substation (sample OCP-SS-052208-02).

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 9

**Direction:** East

**Subject:** Stained soil and distressed vegetation surrounding a transformer pad at the outdoor electrical substation.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 10

**Direction:** West

**Subject:** South portion of the Site, including Areas 7, 8, and 9.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 11

**Direction:** Southeast

**Subject:** Stained soil surrounding three leaking process tanks in Area 7.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 12

**Direction:** East

**Subject:** Abandoned totes in Area 7.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 13

**Direction:** Northwest

**Subject:** Collection of a drum sample for field characterization testing in Area 5.

**Date:** May 22, 2008

**Photographer:** Don McDonald



**Site:** Ohio Cast Products


**Photo Number:** 14

**Direction:** Down

**Subject:** Animal tracks inside the facility, located in the southeast corner of Area 5.

**Date:** May 22, 2008

**Photographer:** Ryan Green



**Site:** Ohio Cast Products

**Photo Number:** 15

**Direction:** West

**Subject:** Surface staining on the western wall of Area 5 from a leaking transformer.

**Date:** May 22, 2008

**Photographer:** Ryan Green