# United States Environmental Protection Agency Region X POLLUTION REPORT

Date: Monday, November 30, 2009

From: Kathy Parker, OSC

To: Debbie Bailey, ODEQ Ken Itel, Clackamas County

Tara Aarnio, Oregon Iron Work

**Subject:** Continuation of Site Work - Week 8

Northwest Pipe and Casing

9585 Mather Road, Clackamas, OR

Latitude: 45.4149000 Longitude: -122.5200000

**POLREP No.:** 9 **Site #:** 10G8

**Reporting Period:** 10/16/09 to 10/24/09 **D.O.** #:

Start Date:8/12/2009Response Authority:CERCLAMob Date:8/12/2009Response Type:Time-CriticalDate:NIN. States:NIN. States:

Demob Date: NPL Status: NPL

Completion Date: Incident Category: Removal Action

CERCLIS ID #: ORD980988307 Contract #

**RCRIS ID #:** ORD980988307

### **Current Activities**

This Polrep covers Site work performed from Friday 10/16/09 through Saturday 10/24/09. Work on site began at 7am and ended at 5:30pm unless otherwise noted.

## Friday 10/16/09

On-site today: OSC Parker, 1 START, 12 ERRS. Safety Meeting at 7 am.

# Excavation:

- \* Continued to excavate and back fill with amended soil the eight foot wide, twenty five foot deep trench in Excavation Area 2, moving westward.
- \* Collected six soil samples from trench walls and one ground water sample from the trench. Also collected one sample of overburden removed from Excavation Area #2.

# Containment Cells:

\* Graded and replaced cap on containment cells 3 through 7 and 9 through 14.

### Water Treatment System:

- \* Continued filling dirty tanks 1 through 4 from both excavations and treated water to clean tanks 6 through 15.
- \* Sampled tanks 6 though 9.

# Other work:

- \* Secured the site for two days without site work.
- \* No dust control performed due to rain.

Saturday 10/17/09 - 2 ERRS pumped and treated groundwater.

Sunday 10/18/09 - 2 ERRS pumped and treated groundwater.

# Monday 10/19/09

On-site today: RPM Ader, 1 START, 13 ERRS. Safety Meeting at 7 am.

Excavation:

- \* Continued to excavate and back fill with amended soil the eight foot wide, twenty five foot deep trench in Excavation Area 2, moving westward.
- \* Collected six soil samples from trench walls

# Containment Cells:

\* Graded and replaced cap on containment cells 2 and 9.

- \* Started again hauling contaminated soil off-site to Subtitle D landfill 29 loads.
- \* Collected soil sample from bottom of containment cell #2.

## Water Treatment System:

- \* Continued filling dirty tanks 1 through 4 from both excavations and treated water to clean tanks 6 through 15.
- \* Collected sample of treated water from tank #10.

#### Other work:

- \* No dust control performed due to rain.
- \* Deconned two inch submersible pump and associated hoses.

# Tuesday 10/20/09

On-site today: RPM Ader, 1 START, 13 ERRS. Safety Meeting at 7 am.

#### Excavation:

- \* Continued to excavate and back fill with amended soil the eight foot wide, twenty five foot deep trench in Excavation Area 2, moving westward.
- \* Started backfilling shoring system #1/ bay #2.
- \* Collected sample of groundwater in the bottom of Excavation Area #1/Shore System 6/ Bay #1.

#### Containment Cells:

- \* Graded and replaced cap on containment cell 1.
- \* Hauled contaminated soil off-site to Subtitle D landfill 36 loads.
- \* Collected soil sample from bottom of containment cell #1.

### Water Treatment System:

- \* Continued filling dirty tanks 1 through 4 from both excavations and treated water to clean tanks 6 through 15.
- \* Discharged 103,700 gallons of treated water to the POTW.

#### Other work:

- \* No dust control performed due to rain.
- \* Deconned 30 ton Haul Truck.

### Wednesday 10/21/09

On-site today: OSC Franklin, 12 ERRS. Safety Meeting at 7 am.

### Excavation:

- \* Continued to excavate and back fill with amended soil the eight foot wide, twenty five foot deep trench in Excavation Area #2, moving westward.
- \* Started to backfill larger area of Excavation Area #2 with clean cap.
- \* Finished backfilling Shoring System #1/ Bay #2.

## Containment Cells:

\* Hauled contaminated soil off-site to Subtitle D landfill - 36 loads.

#### Water Treatment System:

- \* Continued filling dirty tanks 1 through 3 from both excavations and treated water to clean tanks 6 through 9.
- \* Cleaned tanks #14 and #15 and demobilized.
- \* Discharged 72,000 gallons of treated water from tanks #10 through 13 to the POTW.

# Other work:

\* No dust control performed due to rain.

### Thursday 10/22/09

On-site today: OSC Franklin, 1 START, 12 ERRS. Safety Meeting at 7 am.

### Excavation:

- \* Pumped standing water out of excavation area 1/shore system6/bay1.
- \* Finished backfilling Excavation Area #2 to grade with two feet of clean cap.
- \* Started backfilling Excavation Area #1 with overburden and cap material.

# Containment Cells:

\* Loaded out 32 truck loads of soil to subtitle D landfill

### Water Treatment System:

- \* Continued filling dirty tanks 1 and 2 and filling tanks 6 through 9 with treated water.
- \* Cleaned tanks #3 and #4, rinsing water and sediment into tank #1.
- \* Collected treated water sample from tank #6.
- \* Collected one background and three soil samples from the spill area near water treatment tank #1.

#### Other work:

- \* No dust control performed due to rain
- \* L150 Loader demobilized.

## Friday 10/23/09

On-site today: OSC Franklin, 1 START, 11 ERRS. Safety Meeting at 7 am.

### Excavation:

- \* Pumped standing water out of Excavation Area 1/Shore System6/Bay1 and finished backfilling the bay with amended rock and sand.
- \* Continued backfilling Excavation Area #1 with overburden and cap material.
- \* Started backfilling Excavation Area #1 with overburden and cap material.

### Containment Cells:

- \* Loaded out 33 truck loads of soil to subtitle D landfill.
- \* Covered contaminated soil stockpile with visqueen.

# Water Treatment System:

- \* Continued filling dirty tanks 1 and 2.
- \* Cleaned tank #2, rinsing water and sediment into tank #1.
- \* Continued filling tanks #6 through 11 with treated water.
- \* Collected treated water sample from tank #6.
- \* Collected one background soil and three soil samples from the spill area near water treatment tank #1.

#### Other work:

- \* No dust control performed due to rain
- \* Demobilized one load of slide rail shoring, 45kw generator and four inch submersible pump.

## Saturday 10/24/09

On-site today: OSC Franklin, 5 ERRS. Safety Meeting at 7 am.

\* Continued backfilling Excavation Area #1 with cap material.

#### Water Treatment System:

\* Cleaned tanks #12 and #13, rinsing water into tank #11.

#### Other work:

- \* No dust control performed due to rain
- \* Secured site for Sunday off.

## **Planned Removal Actions**

Excavate contaminated soil, backfill and cap to specifications.

# **Next Steps**

- 1. Excavate contaminated soil and transport to appropriate landfill.
- 2. Backfill excavations with adequate compaction
- 3. Include soil amendment in backfill
- 4. Cap excavations with specified capping material

response.epa.gov/nwpc