U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT Mystery Spill -- Ottoville, Ohio - Removal Polrep Final Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region V

Subject: POLREP #4

Final

Mystery Spill -- Ottoville, Ohio

Z5J5

Ottoville, OH

Latitude: 40.9330250 Longitude: -84.3397360

To: Michael Chezik, US Department of Interior

OSLTF USCG, USCG
David Schilt, Ohio EPA
Duty Officer, NRC
Scott Shane, Ohio EPA
Mark Horwitz, USEPA
Jeff Kelley, USEPA
Freddie Thompson, USCG
Kevin Clouse, OEPA
John Tielsch, US EPA
Kaushalya Khanna, US EPA

From: Stephen Wolfe, On-Scene Coordinator

Date: 6/27/2011

Reporting Period: May 12 2010 through June 27, 2011

1. Introduction

1.1 Background

Site Number: B5UK Contract Number: D.O. Number: Action Memo Date:

Response Authority: OPA Response Type: Emergency

Response Lead: EPA Incident Category: NPL Status: Non NPL Operable Unit:

Mobilization Date:12/21/2009Start Date:12/21/2009Demob Date:Completion Date:6/27/2011

CERCLIS ID: RCRIS ID:

ERNS No.: State Notification:

FPN#: E10507 Reimbursable Account #:

1.1.1 Incident Category

Emergency Response -- Mystery Spill

1.1.2 Site Description

see POLREP 1

1.1.2.1 Location

The AOC is located in an alleyway located directly south of 161 West Canal Street, Ottoville, Ohio.

1.1.2.2 Description of Threat

See POLREP 1

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

Inspections indicated that gasoline product was migrating into the storm sewer and that replacement of the old clay storm sewer would remove the threat of oil migrating to the River as well as stopping the odors from migrating into the nearby businesses. All the affected storm sewer was replaced under a PRFA with the Village of Ottoville.

During the replacement of the storm sewer, evidence was found that gasoline was migrating to the storm sewer from the gasoline station. The gasoline station hired a contractor to investigate into the source of the spill.

2. Current Activities

2.1 Operations Section

- 2. Current Activities
- 2.1 Operations Section
- 2.1.1 Narrative

BJAAM installed additional monitoring wells and continues to recover free product from the wells established during the site investigation. No indoor odors have been reported by any of the nearby business owners.

2.1.2 Response Actions to Date

BUSTR continues to enforce ongoing activites at the site. The RP (through their contractors) continues to investigate into the source of the gasoline product and remove the free product from the wells on the gas station property.

2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Manifest #	Treatment	Disposal

2.2 Planning Section

2.2.1 Anticipated Activities

No further involvement form US EPA will be conducted at this site.

BUSTR will contiue to enforce actions at the site

2.2.1.1 Planned Response Activities

None.

2.2.1.2 Next Steps

None.

2.2.2 Issues

None

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

3.1 Unified Command

3.2 Cooperating Agencies

US EPA US Coast Guard Ohio EPA The Village of Ottoville BUSTR

4. Personnel On Site

No information available at this time.

5. Definition of Terms

No information available at this time.

6. Additional sources of information

No information available at this time.

7. Situational Reference Materials

No information available at this time.