

**United States Environmental Protection Agency  
Region III  
POLLUTION REPORT**

**Date:** Monday, August 2, 2004

**From:** Richard Fetzer

**To:** Dennis Carney, EPA Region III  
Linda Marzulli, EPA Region III  
Eric Rooney, PADEP Tank Program

Charlie Kleeman, EPA Region III  
Greg Ham, EPA Region III  
Len Insalaco, PADEP

**Subject:** Emergency Response  
Buckeye Pipeline Emergency Response - Nestle Purina Alpo Plant  
2050 Pope Road, Allentown, PA

<b>POLREP No.:</b>	1	<b>Site #:</b>	993
<b>Reporting Period:</b>	8/2/04 1400 hours	<b>D.O. #:</b>	
<b>Start Date:</b>	8/2/2004	<b>Response Authority:</b>	OPA
<b>Mob Date:</b>	8/2/2004	<b>Response Type:</b>	Emergency
<b>Demob Date:</b>		<b>NPL Status:</b>	
<b>Completion Date:</b>		<b>Incident Category:</b>	
<b>CERCLIS ID #:</b>		<b>Contract #</b>	
<b>RCRIS ID #:</b>		<b>Reimbursable Account #</b>	
<b>FPN#</b>			

**Site Description**

Buckeye Pipeline contractor struck a 16 inch gasoline pipeline with a jack hammer making a 3/4 inch hole. The leak lasted approximately 25 minutes from 0810 hours to 0835 hours. The pipeline was not operating but was pressurized.

No discharge has been detected in waterways. There are 2 permitted drinking water wells within approximately 400 feet of the spill.

**Current Activities**

Local FD on scene monitoring the situation for fire and explosion and discharge abatement.

County EMA responded to scene to assess situation

PADEP Emergency Response and Tank Program responded to scene.

Buckeye Response personnel are on scene and are making repairs to the pipeline and recovering product in order to stabilize the situation.

**Planned Removal Actions**

No action (other than technical assistance) planned or requested by EPA at this time.

**Next Steps**

PADEP will continue to monitor the situation with EPA OSC technical assistance.

PADEP Tank Program will followup with Buckeye with regard to any required groundwater investigation deemed necessary.

PADEP Water Supply program has advised Nestle that they will need to perform quarterly sampling of the 2 drinking water wells approximately 400 feet from the spill.

**Estimated Costs \***

	<b>Budgeted</b>	<b>Total To Date</b>	<b>Remaining</b>	<b>% Remaining</b>
<b>Extramural Costs</b>				
<b>Intramural Costs</b>				

<b>Total Site Costs</b>	\$0.00	\$0.00	\$0.00	0.00%
-------------------------	--------	--------	--------	-------

\* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

[response.epa.gov/Buckeye\\_Alpo](http://response.epa.gov/Buckeye_Alpo)

POLREP #1 Last Updated 8/2/2004