

**United States Environmental Protection Agency
Region I
POLLUTION REPORT**

Date: Wednesday, September 22, 2004

From: Leslie Sims

Subject: 50 Alda Street Oil Spill
50 Alda Street, Bristol, CT
Latitude: 41.2080000
Longitude: -56.8960000

POLREP No.:	2	Site #:	E04114
Reporting Period:		D.O. #:	N/A
Start Date:	4/28/2004	Response Authority:	OPA
Mob Date:	4/28/2004	Response Type:	Emergency
Demob Date:	4/28/2004	NPL Status:	Non NPL
Completion Date:	4/28/2004	Incident Category:	Removal Action
CERCLIS ID #:	N/A	Contract #	N/A
RCRIS ID #:	N/A	Reimbursable Account #	NRC# 719791
FPN#	E0114		

Site Description

A. Incident Category: L
B. Site Description: Leaking Storage Tank
C. Site Location: 50 Alda Street (latitude 41° 41.208' North, longitude 72° 56.896' West), Bristol, CT.

Refer to previous POLREP for Site Description.

Current Activities

Refer to POLREP 1 for previous response activities.

The construction of a permanent sheltered pumping and filtration oil recovery system was completed by CTDEP contractors in July 2004. All of the areas excavated during the initial cleanup have been backfilled and resurfaced. Based on lithological conditions at the Site, CTDEP estimates oil recovery activities will continue throughout the remainder of the year, if not longer. During this period, CTDEP will provide continuous monitoring of the recovery activities on a weekly basis.

Planned Removal Actions

CTDEP will continue supervision and oversight of oil recovery activities and update EPA on a periodic basis regarding the status of the cleanup.

Next Steps

The EPA OSC will continue to provide periodic inspections of the cleanup to ensure continued mitigation is not inconsistent with OPA/NCP cleanup protocol.

Key Issues

This cleanup is being conducted by CTDEP under a EPA-Approved PRFA. At the request of CTDEP the PRFA ceiling was raised from \$50,000 to it's current ceiling of \$95,000. The ceiling increase was based on CTDEP projected costs related to long term monitoring and maintenance-related activities regarding the oil recovery system.

response.epa.gov/50AldaStreetOilSpill