

U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION/SITUATION REPORT
Raritan Bay Slag Site - Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Region II

Subject: POLREP #7
Progress
Raritan Bay Slag Site
NJN000206276
Old Bridge, NJ
Latitude: 40.3879889 Longitude: -74.3352858

To: Tanya Mitchell, USEPA, Region 2, ERRD-SPB

From: Andrew L. Confortini, OSC

Date: 5/9/2013

Reporting Period: 4/20/2013 to 5/08/2013

1. Introduction

1.1 Background

Site Number:	A205	Contract Number:	EP-S2-10-03
D.O. Number:	0059	Action Memo Date:	12/3/2012
Response Authority:	CERCLA	Response Type:	Time-Critical
Response Lead:	EPA	Incident Category:	Removal Action
NPL Status:	NPL	Operable Unit:	RV02
Mobilization Date:	4/1/2013	Start Date:	11/27/2012
Demob Date:		Completion Date:	
CERCLIS ID:	NJN000206276	RCRIS ID:	
ERNS No.:		State Notification:	
FPN#:		Reimbursable Account #:	

1.1.1 Incident Category

On-going release of heavy metals into adjacent soil, sand and water. This release has impacted, and continues to impact nearby beaches and shoreline and sediment within this portion of Raritan Bay. The affected areas are currently being utilized by local fisherman, sun bathers and boaters.

1.1.2 Site Description

The Site is located in the Laurence Harbor section of Old Bridge and in Sayreville along the Raritan Bay. The Site includes Margaret's Creek the Old Bridge Waterfront Park and the western jetty at the Cheesapeake Creek Inlet. The portion of the Site that is situated in Laurence Harbor includes Margaret's Creek and the Old Bridge Waterfront Park. Margaret's Creek is open space consisting of wetland and upland areas. The upland area is reported to be filled with debris containing slag and battery carcasses. The Old Bridge Waterfront Park is made up of walking paths, a playground area, several public beaches, and three jetties, not including the two jetties at the Cheesapeake Creek Inlet. The park waterfront is protected by a seawall, which is partially constructed with pieces of slag. The western jetty at the Cheesapeake Creek Inlet, and the adjoining waterfront area west of the jetty, contains slag as well. The slag was placed at the Site approximately 40 years ago. The seawall, jetties, beach area east of the Cheesapeake Creek Inlet, and the western jetty at the Cheesapeake Creek Inlet are popular fishing areas. The beaches east of the Cheesapeake Creek Inlet and west of the seawall are the most popular for recreation.

EPA has conducted multiple sampling events at the site since 2008 under both the removal and remedial programs. The sampling activities included the collection of soil, sediment, water, biological, and waste samples along the seawall in Laurence Harbor, the western jetty at the Cheesapeake Creek Inlet, the beaches situated near these two locations, and the developed portion of the park. Analytical results generated by EPA indicate that significantly elevated levels of lead and other heavy metals are present in the soils, sediment, and surface water in and around both the seawall in Laurence Harbor and the western jetty at the Cheesapeake Creek Inlet. Analytical results for surface soil samples collected near the seawall were as high as: 142,000 mg/kg for lead, 12,900 mg/kg for antimony, 3,350 mg/kg for arsenic, and 3,590 mg/kg for copper. Soil samples collected on the western jetty at the Cheesapeake Creek Inlet contained lead, at concentrations that ranged from 54,800 mg/kg to 198,000 mg/kg. The maximum concentrations of antimony, arsenic, and copper detected on the western jetty at the Cheesapeake Creek Inlet were 3,120 mg/kg, 2,470 mg/kg, and 4,630 mg/kg, respectively. Nine of 13 soil samples collected in and around the seawall and the western jetty at the Cheesapeake Creek Inlet exceeded the Resource

Conservation and Recovery Act Toxicity Characteristic Leaching Procedure limit for lead (5 mg/l). The TCLP results for the soil from the western jetty exceeded the limit by a magnitude of approximately 100 to 250 times.

Elevated levels of lead were also identified at several surface water locations on the first beach between the western end of the seawall and the first jetty in Old Bridge Waterfront Park. The average lead concentration of the four highest detections at this location was 1,365 ug/l, with a maximum lead concentration of 1,630 ug/l. Three activity-based water samples collected from the beach area situated between the western end of the seawall and the first jetty had an average total lead concentration of 1,179 ug/l, with a maximum total lead concentration of 1,450 ug/l.

Soil samples collected from upland areas in the Margaret's Creek area identified lead, antimony and arsenic at elevated concentrations.

Based on the findings noted above an emergency removal action was implemented by EPA at the site in April and May of 2009 to secure the site and demarcate areas that contained hazardous substances that presented a threat to public health through direct contact

On October 29, 2012 Hurricane Sandy made landfall along the New Jersey coast. The storm surge and high winds caused catastrophic damage along the entire NJ coast. The Site which is located on the Raritan Bay was severely impacted by the storm. The storm surge resulted in severe erosion to the peninsula at Margaret's Creek, erosion of cap material at numerous locations along the top of the seawall, destruction of approximately 2,000 feet of security fence installed to demark contaminated from non contaminated areas, loss of signage notifying the public of health concerns associated with lead and deposition of thousands of tons of sand/debris from potentially contaminated areas onto previously uncontaminated areas that are used by the public for recreation.

1.1.2.1 Location

1.1.2.2 Description of Threat

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

Upon inspection of the Park, large amounts of sand, brick, bundled rubber and fragments, and other general debris were found to be strewn along much grass covered portions of the shoreline. The greatest deposition of material was observed at the eastern end, near Margaret's Creek. In addition, numerous warning signs were observed to have been dislodged from the wooden posts they had been secured to.

The overall approach to this Removal Action was to take the necessary steps to remove the depositional material from the park and place them along the shoreline adjacent to the seawall. In several cases, the mostly sand material from the eastern end of the park was used to re-grade significantly eroded areas adjacent to the playground and walking path.

2.1.2 Response Actions to Date

The following removal action tasks were completed during this reporting period:

:Removal of residual debris from the closed beach;
:Removal of residual debris from the beach west of the closed beach;
:Sampling to re-characterize the site and closed beach for lead contamination;
:Demarcation, removal and off-site disposal of additional impacted sand from portions of the park;
:Installation of security fencing and signage in the Old Bridge Waterfront Park and Sayreville portions of the Site; and
:Restoration of impacted park areas.

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Facility</i>	<i>Disposal</i>
Non-Hazardous, Non-Regulated Debris	Storm Debris	69 tons	N/A	Bayshore Recycling, Inc., Keasby, NJ	Recycled
Non-Hazardous, Non-Regulated Soil	Soil	150 tons	N/A	Cumberland County Solid Waste Complex, Millville, NJ	Landfill

2.2 Planning Section

2.2.1 Anticipated Activities

2.2.1.1 Planned Response Activities

:Seeding of restored areas of the park; and

:Repair/installation of security fencing.

No additional removal actions are planned following the re-installation of the damaged fence.

2.2.1.2 Next Steps

To be determined

2.2.2 Issues

None at this time.

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

No information available at this time.

4. Personnel On Site

No information available at this time.

5. Definition of Terms

No information available at this time.

6. Additional sources of information

No information available at this time.

7. Situational Reference Materials

No information available at this time.