United States Environmental Protection Agency Region II POLLUTION REPORT

Date: Monday, March 5, 2007 Paul L. Kahn & Eric M. Daly From:

To: Mary Mears, USEPA, Region 2, PAD Carole Petersen, USEPA, Region 2ERRD-

NJRB

Patricia Carr, USEPA-PAD

John Kushwara, USEPA Region 2 DECA-

Fred Mumford, NJDEP Marissa Truono, USEPA ERRD-RAB George Zachos, USEPA Region 2 ERRD

Walter Andrews, USEPA Region 2 DEPP-

Andrew Radaant, US DOI Dave Sweeney, NJDEP

Tim Grier, USEPA Headquarters 5202G

Joshua Gradwohl, NJDEP

Carol Chamberlain, Lawrence Township

Health Dept.

Kristin Grun, NJDEP Paul King, NJDEP

Subject: Completion of Emergency Removal Action

Friction Division Products

40 North Enterprise Ave, Lawrence Township (Trenton), NJ

Latitude: 40.2728000 Longitude: -74.7083000

POLREP No.: XW Site #: 16 D.O. #: **Reporting Period:** 6/15/2006 to 6/26/2006 031 **Start Date:** 6/15/2006 **Response Authority: CERCLA** Response Type: **Mob Date:** 1/28/2007 Time-Critical **Demob Date: NPL Status:** Non NPL

Completion Date: 6/26/2006 **Incident Category:** Removal Action **CERCLIS ID #:** NJN0002058677 Contract # EP-W-04-055

RCRIS ID #:

Site Description

This site, a defunct automotive brake pad manufacturer, was brought to the attention of EPA by the NJDEP for a possible referral for a CERCLA removal action. An inspection by EPA OSCs and a DEP responder on 12/23/05 revealed the following hazardous materials/wastes were abandoned at the site: tons of asbestos material, tons of elemental sulphur, 1,000+ drums of mostly unknown materials or materials that do not match the label description, hundreds of smaller containers, acids, flammable liquids, iron and aluminum powders, flammable solids, waste oil, solvents, and other contaminants or pollutants. The Site is semi-controlled, with most doors being locked but numerous open windows or sections of sheet-metal walls missing. A maintenance man is on-site for a few hours Mon-Fri.

During June, 2006, the OSC observed that employees of the RP, Friction Division Products, were entering the Site and loading contaminated drums and debris in a roll-off from Building #7. In the process of removing the contaminated debris they managed to spill powdered chemicals from broken bags on a pallet. EPA brought this to the attention of the property owners. With EPA management authorization, and the owner's permission, EPA initiated security guard service as of June 15, 2006 to prevent access by the RP and other unauthorized persons. Security guard service was discontinued on June 26, 2006, when RP agreed to not enter the Site unless EPA was present.

Current Activities

This POLREP is for administrative purposes only and serves to document the completion of the June 15 -26, 2006, Emergency Response removal action.

Planned Removal Actions

See next POLREP.

Next Steps

See last POLREP.

Key Issues

See last POLREP.

response.epa.gov/frictiondivision