

**United States Environmental Protection Agency  
Region III  
POLLUTION REPORT**

**Date:** Monday, April 2, 2007  
**From:** Don McLaughlin

**Subject:** Sampling at the Site  
Kessel Lumber Supply  
US Highway 50 & US Highway 220, Keyser, WV  
Latitude: 39.3916670  
Longitude: -79.0083330

|                          |   |                            |              |
|--------------------------|---|----------------------------|--------------|
| <b>POLREP No.:</b>       | 4 | <b>Site #:</b>             | WVD016087322 |
| <b>Reporting Period:</b> |   | <b>D.O. #:</b>             |              |
| <b>Start Date:</b>       |   | <b>Response Authority:</b> | CERCLA       |
| <b>Mob Date:</b>         |   | <b>Response Type:</b>      |              |
| <b>Demob Date:</b>       |   | <b>NPL Status:</b>         | Non NPL      |
| <b>Completion Date:</b>  |   | <b>Incident Category:</b>  |              |
| <b>CERCLIS ID #:</b>     |   | <b>Contract #</b>          |              |
| <b>RCRIS ID #:</b>       |   |                            |              |

**Site Description**

The facility was known to use chromated copper arsenate (CCA) to treat fence rails and mine lumber. RCRA had notified the facility regarding the proper disposal of CCA tanks located on-site, but residual product remains on-site with the potential to affect groundwater in the surrounding community.

**Current Activities**

EPA conducted surface and subsurface soil, sediment, and surface water sampling at the facility to determine the need for a potential removal action. Sampling results are pending.

**Planned Removal Actions**

Pending

**Next Steps**

EPA will review the sampling results and determine the need for a removal action based on the sampling data. OSC will meet with the facility owner (RP) and discuss the options for removal of contaminants at the facility.

**Estimated Costs \***

|                         | <b>Budgeted</b> | <b>Total To Date</b> | <b>Remaining</b> | <b>% Remaining</b> |
|-------------------------|-----------------|----------------------|------------------|--------------------|
| <b>Extramural Costs</b> |                 |                      |                  |                    |
| <b>Intramural Costs</b> |                 |                      |                  |                    |
| <b>Total Site Costs</b> | \$0.00          | \$0.00               | \$0.00           | 0.00%              |

\* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

[response.epa.gov/KesselLumber](http://response.epa.gov/KesselLumber)

POLREP #4 Last Updated 4/2/2007