U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION/SITUATION REPORT
Mystery Spill -- Ottoville, Ohio - Removal Polrep
Final Removal Polrep

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Region V

Subject: **POLREP #4**
Final
Mystery Spill -- Ottoville, Ohio
B5UK
Ottoville, OH
Latitude: 40.9330250 Longitude: -84.3397360

To: Mark Durno, U.S. EPA
Jason El-Zein, U.S. EPA
Michael Chezik, US Department of Interior
Beverly Kush, US EPA
Linda Nachowicz, US EPA
OSLTF USCG, USCG
David Schilt, Ohio EPA
Duty Officer, NRC
Scott Shane, Ohio EPA
Mark Horwitz, USEPA
Jeff Kelley, USEPA
Freddie Thompson, USCG
Kevin Clouse, OEPA
John Tielsch, US EPA
Kaushalya Khanna, US EPA
Michelle Jaster, USEPA
Sherry Fielding, U.S. EPA

From: Stephen Wolfe, On-Scene Coordinator
Date: 6/27/2011
Reporting Period: May 12 2010 through June 27, 2011

1. Introduction

1.1 Background

Site Number:	B5UK	**Contract Number:**	
D.O. Number:		**Action Memo Date:**	
Response Authority:	OPA	**Response Type:**	Emergency
Response Lead:	EPA	**Incident Category:**	
NPL Status:	Non NPL	**Operable Unit:**	
Mobilization Date:	12/21/2009	**Start Date:**	12/21/2009
Demob Date:		**Completion Date:**	6/27/2011
CERCLIS ID:		**RCRIS ID:**	
ERNS No.:		**State Notification:**	
FPN#:	E10507	**Reimbursable Account #:**	

1.1.1 Incident Category

Emergency Response -- Mystery Spill

1.1.2 Site Description

see POLREP 1

1.1.2.1 Location

The AOC is located in an alleyway located directly south of 161 West Canal Street, Ottoville, Ohio.

1.1.2.2 Description of Threat

See POLREP 1

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

Inspections indicated that gasoline product was migrating into the storm sewer and that replacement of the old clay storm sewer would remove the threat of oil migrating to the River as well as stopping the odors from migrating into the nearby businesses. All the affected storm sewer was replaced under a PRFA with the Village of Ottoville.

During the replacement of the storm sewer, evidence was found that gasoline was migrating to the storm sewer from the gasoline station. The gasoline station hired a contractor to investigate into the source of the spill.

2. Current Activities

2.1 Operations Section

2. Current Activities
2.1 Operations Section
2.1.1 Narrative

BJAAM installed additional monitoring wells and continues to recover free product from the wells established during the site investigation. No indoor odors have been reported by any of the nearby business owners.

2.1.2 Response Actions to Date

BUSTR continues to enforce ongoing activites at the site. The RP (through their contractors) continues to investigate into the source of the gasoline product and remove the free product from the wells on the gas station property.

2.1.4 Progress Metrics

Waste Stream	*Medium*	*Quantity*	*Manifest #*	*Treatment*	*Disposal*

2.2 Planning Section

2.2.1 Anticipated Activities

No further involvement form US EPA will be conducted at this site.

BUSTR will contiue to enforce actions at the site

2.2.1.1 Planned Response Activities

None.

2.2.1.2 Next Steps

None.

2.2.2 Issues

None

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

2.4.1 Narrative

The Oil Spill Liabilty Trust Fund was accessed for the work since a petroleum product was found in a storm sewer with an unimpeded connection to a navigable waterway.

FPN E10507 was issued for this project.

On April 26, 2010 the FPN was increased to $75,000 and the PRFA with the Village of Ottoville was increased to $70,000.

Estimated Costs *

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
Cooperative Agreements/Letter Contracts	$70,000.00	$40,000.00	$30,000.00	42.86%
Intramural Costs				
USEPA - Direct	$5,000.00	$2,500.00	$2,500.00	50.00%
Total Site Costs	$75,000.00	$42,500.00	$32,500.00	43.33%

* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

3.1 Unified Command

3.2 Cooperating Agencies

US EPA
US Coast Guard
Ohio EPA
The Village of Ottoville
BUSTR

4. Personnel On Site

No information available at this time.

5. Definition of Terms

No information available at this time.

6. Additional sources of information

No information available at this time.

7. Situational Reference Materials

No information available at this time.

POLREP #4 Last Updated 9/8/2021