

MS Resources Operations and Maintenance Report

Supervisor: Zach Purvis

Date: 4/25/2015

Description of Activities and Site Conditions

Site conditions – Overall site is in good condition with little or no visible recoverable oil.

Zone A – No visible recoverable oil.

Zone B – No visible oil was observed, removed emulsified oil with cellu-sorb and replaced cellu-sorb, no absorbent boom was replaced.

Zone C – No visible oil was observed. No work performed.

Material and Amounts Used

Absorbent boom	Pads	Snares	Tools	Trucks 2	Trailers
UTV	Equipment	PPE			

Recommendations:

Site will be checked daily for one week and/or after a 1" rain event.

Sign in:

Zach Purvis		

ZONE A



Seeded and hayed area near well head

ZONE B



Zone B Speed Road with emulsified oil



Zone B Speed Road emulsified oil removed

ZONE C



Zone C Leaf River Church Road no emulsified oil