

MS Resources Operations and Maintenance Report

Supervisor: Travis Smith

Date: 5/26/2015

Description of Activities and Site Conditions

Site conditions – Overall site is in good condition with little or no visible recoverable oil.

Zone A – No visible recoverable oil.

Zone B – No visible oil was observed, oily debris and emulsified oil was removed.

Zone C – No visible oil was observed, a small amount of film buildup at boom set.

Material and Amounts Used

Absorbent boom	Pads	Snares	Tools 1 net	Trucks 1 4x4	Trailers
	Equipment 1 digital camera	PPE	12 drum liners		

Recommendations:

Continue to monitor and clean-up around boom sets after a 1” rain event.

Sign in:

Chase Toussaint		

ZONE B



Zone B Speed Road before



Zone B Speed Road before



Zone B Speed Road after

ZONE C



Zone C Leaf River Church Road before



Zone C Leaf River Church Road after