

Pipeline Oil & Gas Operations and Maintenance Report

Supervisor: Terry White

Date: 06-16-15

Description of Activities and Site Conditions

Site conditions – light rainfall overnight, walked all Divisions, replaced absorbent and recovered oil as needed.

Division A –No Action needed

Division B – No Action needed

Division C – The Tar Creek Site had oil due to rain fall. Oil was recovered for disposal and boom reset. Sorbent Fencing was replaced at GPS N31.27991, W091.09895. All other areas are good with very little oil buildup.

Material and Amounts Used

Absorbent boom	Pads	Snares	Tools	Trucks 2	Trailers
	Equipment	PPE	Sorbent fencing		

Recommendations:

Continue to monitor and clean-up around boom sets daily through Wednesday June 17, 2015 and after a 1/2" rain event.

Sign in:

Terry White		
Jude Collins		

DIVISION C



Division C absorbent fencing before



Division C absorbent fencing after



Division C Tar Creek before



Division C Tar Creek after