

Pipeline Oil & Gas Operations and Maintenance Report

Supervisor: Jude Collins

Date: 06-18-15

Description of Activities and Site Conditions

Site conditions –

Division A –No Action needed

Division B – No Action needed Leaching continues causing minimal sheen and standing oil, but will not be an issue until a heavy rainfall brings the oil up in a substantial quantity.

Division C – No Action needed. Residual leaching continues from embankments, but will not be substantial enough to require action until another heavy rainfall.

Material and Amounts Used

Absorbent boom	Pads	Snares	Tools	Trucks 2	Trailers
	Equipment	PPE			

Recommendations:

Continue to monitor and clean-up around boom sets after a 1/2" rain event. Monitoring will begin on a once a week schedule or after a 1/2" rain event as per the Operations and Maintenance Plan

Sign in:

Terry White		
Jude Collins		