



<b>Photograph No.:</b>	1	<b>Orientation:</b>	West
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 10, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	Entrance to the flammable storage building (FSB).		



<b>Photograph No.:</b>	2	<b>Orientation:</b>	West
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 10, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	Drums D-85, D-86, and D-87 (black drum). The area to the left is the makeshift bed that is held up by flammable containers. START staged the containers in the middle of the building but were scattered throughout the building the next day.		



<b>Photograph No.:</b>	3	<b>Orientation:</b>	West
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 11, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	The southwest corner of FSB where the stained unknown material that overflowed from the spill pallet of drum D-84. Near the stained material were cigarette butts. Drum D-84 had a flashpoint of 86°F.		



<b>Photograph No.:</b>	4	<b>Orientation:</b>	Southeast
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 11, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	The southeast corner of FSB where drum D-82 (labeled Toluene) was located. Drum D-83 (blue drum) and drum D-82 were staged on a spill pallet. The unknown material overflow from the spill pallet to the FSB floor.		



<b>Photograph No.:</b>	5	<b>Orientation:</b>	East
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 10, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	One of the filled cabinets in the research laboratory. It was estimated the research laboratory contain 350 small containers.		



<b>Photograph No.:</b>	6	<b>Orientation:</b>	Southeast
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 10, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	The location of the research laboratory in Bld-1. START estimated that the research laboratory contained over 350 small containers.		



<b>Photograph No.:</b>	7	<b>Orientation:</b>	East
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 10, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	The drum label from D-66 which contained copper dimethyldithiocarbonate. During the inventory reconnaissance, a total of 10 drums (3 in Bld-1 and 7 in Bld-2) were found that contained copper dimethyldithiocarbonate.		



<b>Photograph No.:</b>	8	<b>Orientation:</b>	East
<b>TDD Number:</b>	S05-0808-004	<b>Date:</b>	September 10, 2008
<b>Photographer:</b>	R. Bugg, START	<b>Site Name:</b>	Plabell Rubber Manufacturing Plant
<b>Location:</b>	Toledo, Lucas County, Ohio		
<b>Subject:</b>	Drum D-66 with the specific name and manufacturer label along with the label "Harmful Stow Away from foodstuffs".		