

United States Environmental Protection Agency
Region V
POLLUTION REPORT

Date: Wednesday, April 1, 2009
From: Brian Kelly

Subject: Initial/Final Emergency Response
BUCKEYE PARTNERS PIPE
6969 Boston Rd, Hinckley, OH
Latitude: 41.2767860
Longitude: -81.7355040

POLREP No.:	1	Site #:	E09515
Reporting Period:		D.O. #:	
Start Date:	3/27/2009	Response Authority:	OPA
Mob Date:	3/28/2009	Response Type:	Emergency
Demob Date:	3/28/2009	NPL Status:	Non NPL
Completion Date:	3/29/2009	Incident Category:	Removal Action
CERCLIS ID #:		Contract #	
RCRIS ID #:		Reimbursable Account #	
FPN#	E09515		

Site Description

On March 27, 2009, Buckeye Partners, L.P. reported a potential discharge from a pipeline check valve after finding elevated soil vapor readings. Later Buckeye Partners reported to the On-Scene Coordinator diesel in a trench 20 feet from the pipeline.

The discharge occurred in the parking lot of the Valleaire Golf Course and threatened East Branch Creek.

Current Activities

After being notified of the discovery of diesel, the OSC responded to investigate the release. Once on-site, the OSC reviewed the cleanup activities of the responsible party and issued a notice of federal interest to Buckeye Partners.

Cleanup work included removal of five roll-off boxes of contaminated soil, evacuation of the pipeline, and replacement of the check valve.

Planned Removal Actions

The emergency response has been completed. Final closure of the site will occur under Ohio EPA.

Key Issues

The release is estimated at less than 100 gallons of diesel. No media interest was identified and no wildlife was impacted.

response.epa.gov/buckeye_partners_pipe