

**United States Environmental Protection Agency
Region III
POLLUTION REPORT**

Date: Friday, May 13, 2005

From: Robert Kelly

Subject: Final POLREP
Lake Street Oil Farm
Lake Street, Salisbury, MD

POLREP No.:	3	Site #:	868
Reporting Period:		D.O. #:	
Start Date:		Response Authority:	OPA
Mob Date:		Response Type:	Emergency
Demob Date:		NPL Status:	
Completion Date:		Incident Category:	Removal Assessment
CERCLIS ID #:		Contract #	
RCRIS ID #:		Reimbursable Account #	
FPN#	E04312		

Site Description

A. Lake Street Oil Farm site (site), formerly known as Dale Enterprises, was the location of an oil release of approximately 12,000 gallons in September 1990. In 1994 and 1996, Maryland Department of Environment (MDE) issued notices of violation to the property owners for continued release of oil from the site and improper closure of USTs located onsite.

B. Prior to 2000, U.S. Army Corps of Engineers (USACE) installed an interceptor trench, oil/water collection system, and a bulkhead/retention wall along the perimeter of the site at the Wicomico River.

C. In 1997 through 1999, EPA Site Assessment and Technical Assistance (SATA) contractor performed site assessments to determine site conditions.

D. In 2000 and 2002, USACE contractor conducted assessments and determined the presence of total petroleum hydrocarbons in site soils and groundwater.

Current Activities

- a. START contractor (Tetra Tech) provided OSC Kelly with Trip Report for Site.
- b. Analytical testing revealed there were no petroleum products reaching the Wicomico River.
- c. The assessment, however, did reveal that there were State issues that needed to be addressed.
- d. The OSC has mailed out a letter to the property owner along with a copy of the complete report. The letter informed the owner that though there were no federal removal response activities that fall under OPA or the NCP, the OSC recommended that the owner work with the State to comply with their regulations. The OSC also sent this report to the State.

Planned Removal Actions

No planned removal actions will take place at this Site.

Next Steps

- a. The OSC has determined that there is no further federal actions required at Site at this time.

response.epa.gov/lakestreet