

U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION/SITUATION REPORT
Santee Cooper Sulfuric Acid Release - Removal Polrep
Initial and Final Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Region IV

Subject: POLREP #1
Initial and Final POLREP
Santee Cooper Sulfuric Acid Release

Pineville, SC
Latitude: 33.3716030 Longitude: -80.1144300

To:
From: Brian Englert, FOSC
Date: 11/30/2015
Reporting Period: November 13th

1. Introduction

1.1 Background

Site Number:	B47I	Contract Number:	
D.O. Number:		Action Memo Date:	
Response Authority:	CERCLA	Response Type:	Emergency
Response Lead:	PRP	Incident Category:	Removal Action
NPL Status:	Non NPL	Operable Unit:	
Mobilization Date:	11/13/2015	Start Date:	11/13/2015
Demob Date:	11/13/2015	Completion Date:	
CERCLIS ID:		RCRIS ID:	
ERNS No.:		State Notification:	
FPN#:		Reimbursable Account #:	

1.1.1 Incident Category

Emergency Response to a sulfuric acid spill

1.1.2 Site Description

The Site is the location of a 98% Sulfuric Acid release at Santee Cooper Cross Generation Power Facility. Sulfuric Acid has impacted soil and concrete pads outside of secondary containment and an unknown amount has discharged to a nearby coal ash pond which discharges to the Santee Cooper Channel.

1.1.2.1 Location

The Site is located at 553 Cross Station Road, Pineville, Berkley County, South Carolina 29468, in a rural area. The Site is bordered by Lake Moultrie to the east, wood areas and Lake Marion to the west, forested areas to the north and the Santee Cooper Channel to the South.

1.1.2.2 Description of Threat

An unknown amount of sulfuric acid was released to soil outside of secondary containment and subsequently discharged to a coal ash pond which discharges to the Santee Cooper Channel.

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

On November 13, 2015 at 0846 hours, Santee Cooper Cross Generation Power Facility reported a release of 6,500 gallons of Sulfuric Acid from an above ground storage tank (AST) due to a mechanical failure. The facility is located at 553 Cross Station Road, Pineville, Berkley County, South Carolina 29468. Due to a ruptured water supply line, secondary containment overflowed, and an unknown amount of sulfuric acid impacted nearby soil and concrete pads outside of secondary containment. An additional unknown amount of sulfuric acid and water were pumped into an outfall leading to a nearby coal ash pond to prevent possible impacts to nearby above ground storage tanks and other equipment within the power generation facility. The coal ash pond discharges to the Santee Cooper Channel which joins Lake Moultrie to Lake Marion.

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

In the evening of November 13th, South Carolina Department of Health and Environmental Control (SCDHEC) responded to the scene of a Sulfuric Acid release at Santee Cooper Cross Generation Power Facility to provide oversight. OSC Englert and START were deployed to assist SCDHEC and provide oversight as necessary. OSC Englert met with Santee Cooper Environmental Compliance Staff and Management to see the spill area and discuss ongoing cleanup efforts. Environmental Contractors working

for Santee Cooper neutralized impacted soil and spillage onto concrete pads with limestone (CaCO₃) and soda ash (Na₂CO₃) which will be staged for characterization and disposal at a later date. Crews are making plans to neutralize the material remaining in secondary containment and determine the exact cause of the mechanical failure. EPA and START performed water quality sampling at the influent and effluent of the impacted coal ash pond. All water quality parameters were within expected ranges; pH readings in influent and effluent sample locations were 7.6 and 7.1 respectively indicating that the coal ash pond had effectively buffered any Sulfuric Acid discharged into it. SCDHEC, EPA and START demobilized on November 13th.

2.1.2 Response Actions to Date

SCDHEC, EPA and START mobilized to the Site

EPA and START have taken water quality samples

SCDHEC, EPA and START have demobilized

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

Enforcement activities have been initiated and are ongoing. The spill occurred at Santee Cooper Cross Generating Facility located 553 Cross Station Road, Pineville, Berkley County, South Carolina 29468. The facility is owned by Santee Cooper who has been identified as the Potentially Responsible Party (PRP).

2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Treatment</i>	<i>Disposal</i>
N/A					

2.2 Planning Section

2.2.1 Anticipated Activities

No further activities are anticipated

2.2.1.1 Planned Response Activities

No further response activities are planned

2.2.1.2 Next Steps

EPA response activities are complete

2.2.2 Issues

No issues encountered

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

No information available at this time.

4. Personnel On Site

Santee Cooper Management, Environmental Staff and facility staff

One EPA OSC

Two START Contractors

5. Definition of Terms

No information available at this time.

6. Additional sources of information

6.1 Internet location of additional information/report

Please see www.epaosc.org/santeecoopersulfuricacid

6.2 Reporting Schedule

7. Situational Reference Materials

No information available at this time.