

Appendix E
Recommended Stabilization Plan (2003)
Quincy Smelter Site
Asbestos Abatement Assessment
December 2004

Building Number	Building Name	Recommended Stabilization Plan
2	Dockside Warehouse	Remove loose corrugated metal roofing and patch roof; asbestos abatement; remove unstable shed addition; construct frame wall along the column line of shed addition to prevent weather damage; dispose of glass and debris.
3	Laboratory	and debris.
5	Casting Plant	Asbestos abatement; repair steel column base corrosion; remove corrugated metal roofing, siding and loose building components; cable metal stack in furnace building; install corrugated metal roofing and siding over the entire structure; install translucent panels over window openings; remove loose sandstone from SW corner of furnace building and install kneewall; dispose of glass and debris.
6	No. 5 Reveratory Furnace Building	
7	Reveratory Furnace Building	
7	Reveratory Furnace Smokestack	Ranges from guy wire replacement, to demolition, to total stack rehab.
11	Cooper Stock Building	Window coverings; dispose of glass and debris.
13	Limestone Building	Remove loose overhead materials; cable loose members; dispose of glass and debris.
14	Briquetting Plant	Remove timbers and roof debris from upper levels; brace interior column; masonry repairs at building sill; brace existing wood trusses where missing or absent; remove corrugated metal roofing where badly deteriorated or loose; install wood purlins over trusses; intall corrugated metal roof over purlins; partition east wall to limestone bins.
15	Crushing Plant	Patch roof; asbestos abatement; dispose of glass and debris.
16	Pump House	
17	Cupola Furnace Building	
18	Boiler House	Remove timbers, unsecured line shafting and roof debris from 2nd floor; remove corrugated metal roofing and siding; remove loose masonry; brace small chimney stack above forge; install new corrugated metal roof structure on posts outside of existing building; asbestos abatement; dispose of glass and debris.
19	Baden Hausen Boiler Building	
20	Machine Shop	Not discussed.
25	Barn	
27	House	

Source: Franklin Township and Keewenaw National Historical Park, Stabilization Plan, Quincy Mining Company Smelting Works (February 2003).