

Pipeline Oil & Gas Operations and Maintenance Report

Supervisor: Jude Collins

Date: 07-24-15

Description of Activities and Site Conditions

Site conditions – Tank Battery has been relocated.

Division A –No action needed. All Sorbent Fencing is still in place pending MDEQ directions for removal.

Division B – No Action needed

Division C – No Action needed.

Material and Amounts Used

Absorbent boom	Pads	Snares	Tools	Trucks 2	Trailers
	Equipment	PPE			

Recommendations:

Continue to monitor and clean-up around sorbent fencing after a 1/2" rain event. No visible oil leaching in dry creek bed at this time. All fencing removed except in zone A just below previous tank battery.

Sign in:

Jude Collins		
Jarred Haley		