

**United States Environmental Protection Agency
Region III
POLLUTION REPORT**

Date: Thursday, February 26, 2009
From: Laura Casillas, Chris Wagner

To: Fran Burns, USEPA R3 EPA RRC EPA RRC, EPA RRC

Subject: Second Round of Residential Well Sampling Complete
Allied Terminals Response
501 Hill Street, Chesapeake, VA
Latitude: 36.7955654
Longitude: -76.2870026

POLREP No.:	12	Site #:	A3MD
Reporting Period:	1/17/2009-2/27/2009	D.O. #:	
Start Date:	11/12/2008	Response Authority:	CERCLA
Mob Date:		Response Type:	Emergency
Demob Date:		NPL Status:	Non NPL
Completion Date:		Incident Category:	Removal Assessment
CERCLIS ID #:		Contract #	
RCRIS ID #:			

Site Description

This polrep focuses on Site activities from January 17th, 2008 through February 27, 2008. For more information regarding the incident or EPA's previous activities, please see previous polreps.

The Chesapeake Fire Dept. requested that EPA maintain a presence on the Site until work in the residential areas was completed.

Current Activities

During this period EPA sampled drinking water wells at two residences on Bannister street for Nitrates and Nitrites. On January 26, 2009 EPA received permission from homeowners to take the samples. EPA returned on Wednesday February 4, 2009 to sample the wells.

EPA OSC Laura Casillas received validated analytical data on February 25, 2009. The data shows that Nitrates and Nitrites were not detected. Nitrates and Nitrite levels are within safe drinking water parameters. Results are posted under the documents section of the www.epaosc.org allied terminals site.

Allied terminals continues to pump residues that flow onto the ditches and to do weekly air monitoring.

Key Issues

EPA will continue to monitor the status of residues that make their way onto street ditches.

Allied is working with the VDEQ to address potential storm water permitting issues from potential off-site migration of fertilizer residues.

Estimated Costs *

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
Intramural Costs				
Total Site Costs	\$0.00	\$0.00	\$0.00	0.00%

* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the

government may include in any claim for cost recovery.

response.epa.gov/AlliedTerminalsResponse

POLREP #12 Last Updated 2/26/2009