

**United States Environmental Protection Agency
Region IV
POLLUTION REPORT**

Date: Wednesday, October 21, 2009
From: Randy Nattis, OSC

To: Matt Taylor, USEPA R4 ERRB Jim McGuire, USEPA R4 ERRB

Subject: Initial POLREP
Old River Road Transformer
Juliette, GA
Latitude: 33.0951864
Longitude: -83.7817705

POLREP No.:	1	Site #:	
Reporting Period:	10/20/2009	D.O. #:	
Start Date:	10/20/2009	Response Authority:	CERCLA
Mob Date:	10/20/2009	Response Type:	Emergency
Demob Date:		NPL Status:	Non NPL
Completion Date:		Incident Category:	Removal Action
CERCLIS ID #:		Contract #	
RCRIS ID #:			

Site Description

8-10 transformers labeled with PCBs were uncovered during construction. One transformer was breached, releasing PCBs to the soil. OSC Randy Nattis dispatched. Site is approximately 800 feet from the Ocmulgee River.

Current Activities

OSC Nattis arrived on site at approximately 1545 and met with owner who unearthed the containers during site construction. OSC Nattis identified the containers and verified the PCB labels and the condition of the containers. At least two of the containers were breached and oils containing PCB materials were leaking into an unlined ditch. OSC Nattis isolated the area and will return first thing 10/21/09 with an ERRS crew to over pack the transformers and oil contaminated soils.

Planned Removal Actions

OSC Nattis will work with GA EPD and EPA Removal for possible enforcement activities and assessment activities, respectively

Estimated Costs *

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
ERRS - Cleanup Contractor	\$20,000.00	\$0.00	\$20,000.00	100.00%
Intramural Costs				
Total Site Costs	\$20,000.00	\$0.00	\$20,000.00	100.00%

* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

response.epa.gov/oldriverroadtransformer