

**United States Environmental Protection Agency  
Region IV  
POLLUTION REPORT**

**Date:** Monday, August 29, 2011  
**From:** Perry Gaughan, OSC

**Subject:** and Final - Waterline Hookups Completed  
Southside Road  
Lincolnton, NC  
Latitude: 35.4764290  
Longitude: -81.2401280

<b>POLREP No.:</b> 2	<b>Site #:</b>
<b>Reporting Period:</b> Sept 1 through October 15, 2009	<b>D.O. #:</b>
<b>Start Date:</b> 7/22/2009	<b>Response Authority:</b> CERCLA
<b>Mob Date:</b> 7/22/2009	<b>Response Type:</b> Emergency
<b>Demob Date:</b> 10/15/2009	<b>NPL Status:</b> Non NPL
<b>Completion Date:</b> 10/15/2009	<b>Incident Category:</b> Removal Action
<b>CERCLIS ID #:</b>	<b>Contract #</b>
<b>RCRIS ID #:</b>	

**Site Description**

In late July 2009, NC DENR requested EPA Reg 4 assistance with assessing several contaminated drinking water wells around the Charlotte, NC area. ERRB Reg 4 began assessing twelve sites in a five county area and obtained access agreements from potentially contaminated homes around each of these sites.

**Current Activities**

During July and August 2009, several drinking water wells along Southside Road were sampled for chlorinated solvents and three wells were identified as exceeding EPA's action level, 1878 Southside (55 ppb PCE), 1904 Southside (50 ppb PCE), and 1938 Southside (45 ppb PCE).

The OSC, working with the Phone Duty OSC, drafted an emergency action memo and task order to fund waterline hook ups with all three affected homes under CERCLA. Discussions were held with all three residents and they agreed to have their homes hooked up to the waterline which paralleled Southside Road. ERRs contractors tasked local contractors to complete the waterline hook ups and all efforts were coordinated with the Lincoln County Water Authority.

**Next Steps**

No further actions are anticipated.

**Estimated Costs \***

	Budgeted	Total To Date	Remaining	% Remaining
<b>Extramural Costs</b>				
ERRS - Cleanup Contractor	\$40,000.00	\$21,169.00	\$18,831.00	47.08%
RST/START	\$10,000.00	\$4,000.00	\$6,000.00	60.00%
<b>Intramural Costs</b>				
USEPA - Direct (Region, HQ)	\$5,000.00	\$2,800.00	\$2,200.00	44.00%
<b>Total Site Costs</b>				
	\$55,000.00	\$27,969.00	\$27,031.00	49.15%

\* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

[response.epa.gov/SouthsideRoadWellsSite](http://response.epa.gov/SouthsideRoadWellsSite)

POLREP #2 Last Updated 9/23/2011