

U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION/SITUATION REPORT
Manweiler Trucking Spill - Removal Polrep
Final Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Region VIII

Subject: POLREP #3
Response Close-Out
Manweiler Trucking Spill
Colorado Springs, CO
Latitude: 38.8220000 Longitude: -104.8380000

To: Tara Kelley, Colorado Springs Utilities
Gordon Brenner, Colorado Springs Office of Emergency Management
Michael Dalton, Colorado Springs Fire Department
Tom Gonzales, El Paso County Public Health
Richard Smith, El Paso County Office of Emergency Management
Mark Mears, Pueblo County Sheriff Department
Shawn Shelton, Pueblo Fire Department
Gregory Stasinos, CDPHE
Bob Hildebrand, United States Coast Guard
Martin Hestmark, EPA Region 8

From: Martin Mccomb, Federal On Scene Coordinator and Lisa McClain-Vanderpool, Public Information Officer

Date: 10/4/2017

Reporting Period: Post Response

1. Introduction

1.1 Background

Site Number:	Contract Number:
D.O. Number:	Action Memo Date:
Response Authority: OPA	Response Type: Emergency
Response Lead: EPA	Incident Category: Removal Action
NPL Status: Non NPL	Operable Unit: n/a
Mobilization Date: 8/26/2016	Start Date: 8/26/2016
Demob Date: 8/27/2016	Completion Date: 12/31/2016
CERCLIS ID:	RCRIS ID:
ERNS No.:	State Notification:
FPN#: E16804	Reimbursable Account #:

On August 26, 2016, the Colorado Springs Fire Department (CSFD) reported an accident involving a fuel tanker belonging to Manweiler Transport. The accident happened at approximately 0400 that day near 911 Motor City Drive in Colorado Springs, El Paso County, Colorado. CSFD estimated from the size of the tanker and the amount of recovered material that nearly 6000 gallons of unleaded gasoline and 2000 gallons of diesel fuel were released. CSFD reported that all but a few hundred gallons of this released material had entered into a storm drain that empties into Bear Creek just above its confluence with Fountain Creek. Free product, sheen and a fish kill was witnessed in Fountain Creek.

Colorado Springs Utilities (CSU) closed the intake to the Fountain Mutual Irrigation Canal located near CSU's Las Vegas Water Resource Recovery Facility. CSU also notified downstream agricultural water users to close and/or monitor their intakes. Colorado Springs Utilities did not identify any downstream public water user intakes that required notification.

2. Current Activities

2.1 Operations Section

See Pollution Report #1 for additional details on Operations that occurred August 26-30, 2016,

EPA's team collected visible observations and samples from several downstream water intakes and boom locations on Friday, August 26 and Saturday, August 27, 2016, to determine the presence or absence of petroleum hydrocarbons at the time the locations were visited. The samples were analyzed for both Gasoline Range Organics (GRO) and Diesel Range Organics (DRO). The preliminary laboratory data shows that hydrocarbons were detected between the location of the spill and Fountain Creek Regional Park on the first day. The highest results on August 26 were DRO at 3.27 mg/l at Fountain Creek Regional Park and

GRO at 1.48 mg/l at the closed intake to the Fountain Mutual Irrigation Canal. On August 27, these levels had reduced to 0.2 mg/l and 0.182 mg/l respectively. Little or no hydrocarbons were detected downstream of Fountain Creek Regional Park on either day. These observations and samples confirm that the spill did not have a lasting impact on the use of Fountain Creek for irrigation and that all diversions can be reopened.

The results from the lab are posted at <https://epaossc.org/ManweilerTruckingSpill> and are also accessible in EPA's web mapping tool: <https://r8.ercloud.org/ManweilerTruckingSpill>.

Here are some tips for using the web map:

1. When you open the link, you are viewing the mapping tool used by EPA's field operations. The operational layers that can be used accessed in the map are listed on the left side of the screen.
2. You can navigate data types and decipher symbols on the map by clicking on the arrow symbols before each operational layer. You can also turn layers on and off by using the check boxes. Note that if you are trying to display layers, you will need to check the boxes next to both the data type (such as "Site Data") and the layer that you want to display.
3. Functionalities such as draw and measure are provided as icons located in the upper left part of the screen.
4. Click on symbols and/or areas of the map to obtain additional information. When you do so, a pop-up window will appear and you may have to use the navigation arrows at the top of the window to scroll through multiple pop-ups.

2.2 Planning Section

EPA will close the site and archive the data that was collected.

2.3 Logistics Section

EPA demobilized from the site on August 27, 2016.

2.4 Finance Section

A cost ceiling with the Oil Spill Liability Trust Fund has been established at \$100,000. The ceiling was established to give the FOSC the flexibility of calling in additional resources.

Estimated Costs *

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
START	\$30,000.00	\$25,000.00	\$5,000.00	16.67%
Contingency	\$40,000.00	\$0.00	\$40,000.00	100.00%
Intramural Costs				
USEPA - Direct	\$14,317.00	\$10,000.00	\$4,317.00	30.15%
USEPA - InDirect	\$15,683.00	\$12,000.00	\$3,683.00	23.48%
Total Site Costs	\$100,000.00	\$47,000.00	\$53,000.00	53.00%

* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

2.5 Other Command Staff

Lisa McClain-Vanderpool is the designated EPA Public Information Officer (PIO).

3. Participating Entities

Belfor Environmental (response contractor)
Colorado Department of Public Health and Environment
Colorado Springs Fire
Colorado Springs Utilities
Colorado Springs Office of Emergency Management
Custom Environmental Services (response contractor)

El Paso County Health Department

El Paso County Office of Emergency Management

Pueblo County Sheriff

Pueblo Fire

United States Coast Guard

United States Environmental Protection Agency

4. Personnel On Site

None.

5. Definition of Terms

CSFD: Colorado Springs Fire Department

CSU: Colorado Springs Utilities

FOSC: Federal On Scene Coordinator

START: Superfund Technical Assistance and Response Team

6. Additional sources of information

<https://epaossc.org/ManweilerTruckingSpill>

7. Situational Reference Materials

A map of the response can be viewed at:

<https://r8.ercloud.org/manweilertruckingspill/>

POLREP #3 Last Updated 11/3/2017