




Figure A1. DOUBLE H Site A
1501 Bethany Road, Grandview, WA



Approximate locations of pits and soil piles are shown above. Dotted lines indicate soil piles. "Ts 1-9" represent approximate locations of transects 1-9.