



Official Photograph No. 1

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of WGE Belton Facility.		



Official Photograph No. 2

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of WGE Belton Facility entrance.		



Official Photograph No. 3

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View at the back of the warehouse.		



Official Photograph No. 4

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of second storage building.		



Official Photograph No. 5

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Containers of lead impacted material.		



Official Photograph No. 6

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of scrap metal recovered from shooting ranges.		



Official Photograph No. 7

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Metal baffles from shooting ranges.		



Official Photograph No. 8

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Evidence of expended shell casings.		



Official Photograph No. 9

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Close-up view of expended shell casings.		



Official Photograph No. 10

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of drum storage area.		



Official Photograph No. 11

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of drum storage & debris field.		



Official Photograph No. 12

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View drums of hardened salt 'NuSal' at the front of the property.		



Official Photograph No. 13

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of label from hardened salt 'NuSal' drums.		



Official Photograph No. 14

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of debris field.		



Official Photograph No. 15

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Additional debris.		



Official Photograph No. 16

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of drums of hardened salt 'NuSal' at the back of the property.		



Official Photograph No. 17

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	View of spent casings.		



Official Photograph No. 18

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Buckets of spent casings open to elements.		



Official Photograph No. 19

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Additional drums.		



Official Photograph No. 20

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Inside second storage building range rubber used to stop bullets.		



Official Photograph No. 21

Site Name:	WGE Belton Facility	Date:	January 31, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Close up of spent bullets embedded in the rubber material.		



Official Photograph No. 22

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Equipment stored in the warehouse.		



Official Photograph No. 23

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Conveyor used to recover spent casings and bullets.		



Official Photograph No. 24

Site Name:	WGE Belton Facility	Date:	February 2, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Warehouse floor determined to be impacted with lead concentrations.		



Official Photograph No. 25

Site Name:	WGE Belton Facility	Date:	February 18, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Drums secured in the warehouse.		



Official Photograph No. 26

Site Name:	WGE Belton Facility	Date:	February 18, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Steel containers secured in the warehouse.		



Official Photograph No. 27

Site Name: WGE Belton Facility
Location: Belton, Anderson County, South Carolina
Photographer: Jerry Partap, START
Subject: Drums secured at the front of the property.

Date: February 18, 2011
TDD No: TNA-05-001-0127



Official Photograph No. 28

Site Name: WGE Belton Facility
Location: Belton, Anderson County, South Carolina
Photographer: Jerry Partap, START
Subject: Drums secured at the back of the property.

Date: February 18, 2011
TDD No: TNA-05-001-0127



Official Photograph No. 29

Site Name:	WGE Belton Facility	Date:	February 18, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Silt fencing.		



Official Photograph No. 30

Site Name:	WGE Belton Facility	Date:	February 18, 2011
Location:	Belton, Anderson County, South Carolina	TDD No:	TNA-05-001-0127
Photographer:	Jerry Partap, START		
Subject:	Silt fencing.		