

WGE Fairplay, SC- Fairplay

Progress Notes

Date: March 21, 2011

1. Decontamination of excavator. Washed excavator with water and simple green solution, brushed and rinsed, sprayed with vinegar allowed to soak and rinsed. Will check readings with xrf on 3-22-2011
2. All solid waste, PPE (suits, gloves, and rags) disposed of in a contractor trash bag sealed with tape and lead hazard sticker placed on bag. Liquid vacuumed and disposed of in 55 gallon DOT approved drums.
3. Waste generated was, lead, Tyvek suites and gloves, rags, lead contaminated soil, and water simple green and vinegar.
4. Completed approximately 100% of decontamination, will verify results on Tuesday March 22, 2011
5. Crew size was one supervisor and one worker.

Report Submitted By: Scott Shaw (Safety Coordinator)

welchgroupsafety@gmail.com

Welch Group Environmental

118 White Oak Road

Belton, SC 29627

864-446-0405