

WGE Belton, SC- PALMETTO Site

Progress Notes

Date: June 23 2011

1. Continued boxing up and shrink wrapping miscellaneous debris in area c for disposal that could not be decontaminated.
2. All solid waste, PPE (suits, gloves, and rags) disposed of in a contractor trash bag sealed with tape and lead hazard sticker placed on bag.
3. Waste generated was Tyvek suites, gloves, and rags.
4. Completed approximately 10% of prepping miscellaneous debris for disposal in area c.
5. Crew size was one supervisor and four workers.

Report Submitted By: Scott Shaw (Safety Coordinator)

[welchgroupsafety@gmail.com](mailto:welchgroupsafety@gmail.com)

Welch Group Environmental

118 White Oak Road

Belton, SC 29627

864-462-0405