



Mechanical brush clearing



Straw waddles



Brush clearing complete



Site view—Rail Trail



Tree clearing



ACS Placement cap



ACS Removed Area



Beginning of placement area



Placement area -- ACS covered



Tree Clearing



Railroad tie removal/clearing
Placement area



Tree chipping operation



Clean railroad ties



Test pit—Gas Pipeline



ACS Removal



Wetlands - ACS removal



Wetlands prior to backfill



Wetlands soil backfill



ACS area removed and covered - waiting analytical results



Wetlands - ACS removal



Swamp mat bridge



Wetlands soil backfill



Wetlands / ACS area hydro-seeded



Wetlands hydro-seeded



Placement area cap preparation



Fabric placement cap

Gas Pipeline excavation





Pipeline flooding



Placement area cap preparation



Curtain drain installation



Heavy equipment crossing bridge
over pipeline



ACS cap - Fill placement



Hydro-seeding rail trail



Gas pipeline hydro-seeded



Coconut mat—Erosion control



Coconut mat—Erosion control



ACS cap prior to winter



View of landfill cap facing west



View of landfill cap facing northeast.



Elastomerics looking north



Elastomerics looking south



Railroad Right-of-Way looking east



Cernak Parcel



Railroad Right-of-Way
looking west



Placement Cap looking east along railroad right-of-way



Tennessee Gas easement looking north



Placement Cap looking west
toward Site building



Placement Cap looking south



Placement Cap looking east



Tennessee Gas easement looking
east towards placement area



Border with DOS property
looking west



Vermiculite in ceiling areas



Main office during abatement