



ATTACHMENT D
Photographic Documentation

ECOLOGY AND ENVIRONMENT, INC.
Superfund Technical Assessment and Response Team
Mojave River Pyrotechnics Removal
Barstow, San Bernardino County, California

E&E Project. No.: EE-002693-2202

TDD No: TO2-09-12-10-0001

Contract No. EP-S5-08-01



PHOTO 1

Date: 12/04/12

Direction: Northeast

Photographer: Robin Clemens

Description: View of ERRS constructing haul road through the site.



PHOTO 2

Date: 12/04/12

Direction: South

Photographer: Robin Clemens

Description: View of ERRS excavating trash pile area and performing dust suppression via application of water spray. Dust monitoring instrument visible in lower right quadrant of image.



PHOTO 3

Date: 12/05/12

Direction: Northwest

Photographer: Robin Clemens

Description: View of ERRS loading excavated contaminated soil from trash pile area into a haul truck.

ECOLOGY AND ENVIRONMENT, INC.
Superfund Technical Assessment and Response Team
Mojave River Pyrotechnics Removal
Barstow, San Bernardino County, California

E&E Project. No.: EE-002693-2202

TDD No: TO2-09-12-10-0001
Contract No. EP-S5-08-01



PHOTO 4

Date: 12/06/12

Direction: East

Photographer: Matthew Diener

Description: View of ERRS installing a PVC liner in trash pile area.



PHOTO 5

Date: 12/06/12

Direction: Down

Photographer: Matthew Diener

Description: View of white material encountered during excavation in garden area, consistent with perchlorate product found during the removal assessment.



PHOTO 6

Date: 12/08/12

Direction: Northwest

Photographer: Matthew Diener

Description: View of partially installed liner in garden area. Backfill with clean fill sand in progress.