

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 1

Direction: Northeast

Subject: Preparation of staging / sampling pad at north end of site

Date: 10-Oct-2013

Photographer: D.Robinson



Site: Parish Chemical Removal Action

Photograph No.: 2

Direction: South

Subject: Pre-work view of drum yard on the west side of the Parish facility.

Date: 10-Oct-2013

Photographer: D.Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 3

Direction: West

Subject: START prepares sample bottles and supplies for drum sampling

Date: 11-Oct-2013

Photographer: D. Robinson



Site: Parish Chemical Removal Action

Photograph No.: 4

Direction: Northwest

Subject: Sampling pad showing Level of Protection flags at perimeter

Date: 11-Oct-2013

Photographer: D. Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 5

Direction: Northwest

Subject: Sampled drum in overpack showing sample ID system and sample jar.

Date: 15-Oct-2013

Photographer: D. Robinson



Site: Parish Chemical Removal Action

Photograph No.: 6

Direction: West

Subject: START and ERRS conducting Level B sampling of unknown drums.

Date: 17-Oct-2013

Photographer: D. Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 7

Direction: Northwest

Subject: Drum yard west of facility – drums removed to staging area.

Date: 17-Oct-2013

Photographer: D. Robinson



Site: Parish Chemical Removal Action

Photograph No.: 8

Direction: Northeast

Subject: START and ERRS conducting Level B sampling of unknown drums.

Date: 17-Oct-2013


Photographer: D. Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action
Photograph No.: 9
Direction: Southeast
Subject: Hazcatting lab setup inside facility lower level.

Date: 17-Oct-2013
Photographer: D. Robinson



Site: Parish Chemical Removal Action
Photograph No.: 10
Direction: East
Subject: Drum of halogenated organic liquid staged in waste disposal pad.

Date: 19-Oct-2013
Photographer: D. Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 11

Direction: Northwest

Subject: Drum yard west of plant looking northwest from aisle way.

Date: 19-Oct-2013

Photographer: D.Robinson



Site: Parish Chemical Removal Action

Photograph No.: 12

Direction: West

Subject: Pallets of commonly-labeled drums removed from drum yard and staged for sampling.

Date: 19-Oct-2013

Photographer: D. Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 13

Date: 19-Oct-2013

Direction: Northwest

Photographer: D. Robinson

Subject: Drums of sampled waste staged in waste disposal yard awaiting classification.



Site: Parish Chemical Removal Action

Photograph No.: 14

Date: 19-Oct-2013

Direction: Southeast

Photographer: D. Robinson

Subject: Waste containers segregated in waste disposal pad awaiting classification.

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 15

Direction: Northwest

Subject: Sampled totes of flammable waste staged on waste pad awaiting classification.

Date: 19-Oct-2013

Photographer: D. Robinson



Site: Parish Chemical Removal Action

Photograph No.: 16

Direction: Northeast

Subject: ERRS relocating sampling pad near building after removal of drums from area.

Date: 19-Oct-2013

Photographer: D. Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 17

Direction: Northwest

Subject: Documentation of drums in drum yard by ERRS

Date: 09-Oct-2013

Photographer: D.Robinson



Site: Parish Chemical Removal Action

Photograph No.: 18

Direction: West

Subject: Good-condition label on drum of Germanium process waste in drum yard

Date: 09-Oct-2013

Photographer: D. Robinson

Parish Chemical Removal Action – Photo Log, 20-Oct-2013



Site: Parish Chemical Removal Action

Photograph No.: 19

Direction: Northeast

Subject: Severely rusted drum on waste staging pad (empty)

Date: 19-Oct-2013

Photographer: D. Robinson



Site: Parish Chemical Removal Action

Photograph No.: 20

Direction: East

Subject: Dry storage room for water reactive chemicals on lower level of facility.

Date: 19-Oct-2013

Photographer: D. Robinson