

Table 3: Additional Assessment Sample Results
(Collected During Removal)

| Sample Number | Lab ID Number | Sample Location | Date Collected | Date Analyzed | Collection Type | Collection Depth (bgs) | PLM Results | Notes |
|--|---------------|----------------------------------|----------------|---------------|-----------------|------------------------|-------------|--|
| Backfill Samples | | | | | | | | |
| BF01_111113_06 | 132309-S1 | Backfill Borrow Pit | 11/11/2013 | 11/15/2013 | Grab | 0-6 in | NAD | - |
| BF012_111113_06 | 132309-S2 | Backfill Borrow Pit | 11/11/2013 | 11/15/2013 | Grab | 0-6 in | NAD | - |
| BF02_111113_06 | 132309-S3 | Backfill Borrow Pit | 11/11/2013 | 11/15/2013 | Grab | 0-6 in | NAD | - |
| CM01_111113_06 | 132309-S4 | Backfill Borrow Pit | 11/11/2013 | 11/15/2013 | Grab | 0-6 in | NAD | - |
| CM012_111113_06 | 132309-S5 | Materials Storage Yard | 11/11/2013 | 11/15/2013 | Grab | 0-6 in | <0.25% | - |
| CM02_111113_06 | 132309-S6 | Materials Storage Yard | 11/11/2013 | 11/15/2013 | Grab | 0-6 in | NAD | - |
| CMB01_111613_06 | 132365-S1 | Materials Storage Yard | 11/16/2013 | 11/20/2013 | Grab | 0-6 in | NAD | - |
| CMB12_111613_06 | 132365-S2 | Materials Storage Yard | 11/16/2013 | 11/20/2013 | Grab | 0-6 in | NAD | - |
| CMB02_111613_06 | 132365-S3 | Materials Storage Yard | 11/16/2013 | 11/20/2013 | Grab | 0-6 in | NAD | - |
| Area A (W. Silver Recycling Facility) | | | | | | | | |
| SWV2_CWA_1218 | 140048-S8 | Area A, Grid C - West | 1/8/2014 | 1/14/2014 | 5-pt Composite | 0-6 in | <0.25% | Assessment: After 1 ft excavation (5-pt composite) |
| SWV2_DWA_1218 | 140048-S9 | Area A, Grid D - West | 1/8/2014 | 1/14/2014 | 5-pt Composite | 0-6 in | NAD | Assessment: After 1 ft excavation (5-pt composite) |
| SWV2_EA1_1218 | 132574-S1 | Area A, Grid E, subgrid 01 | 12/13/2013 | 12/17/2013 | 5-pt Composite | 0-6 in | NAD | Assessment: After 1 ft excavation (5-pt composite) |
| W. Silver Recycling Warehouse | | | | | | | | |
| SWVSoil_WAR1W | 132523-S1 | Auxillary West part of warehouse | 12/9/2013 | 12/13/2013 | Composite | 0-1 in | NAD | Floor/Sweeping |
| SWVSoil_WAR2E | 132523-S2 | Auxillary East part of warehouse | 12/9/2013 | 12/13/2014 | Composite | 0-1 in | NAD | Floor/Sweeping |

Legend:

bgs - below ground surface

NAD - No Asbestos Detremined