

## MS Resources Operations and Maintenance Report

Supervisor: Travis Smith

Date: 6/8/2015

### Description of Activities and Site Conditions

Site conditions – Overall site is in good condition with little or no visible recoverable oil.

Zone A – No visible recoverable oil.

Zone B – No visible oil was observed, debris buildup at boom, debris removed.

Zone C – No visible oil was observed, debris buildup at boom, debris removed.

### Material and Amounts Used

Absorbent boom	Pads	Snares	Tools 1 net	Trucks 1 4x4	Trailers
	Equipment 1 digital camera	PPE	6 drum liners		

### Recommendations:

UC walkthrough from 84 to speed road, if no visible oil, remove boom.

### Sign in:


## ZONE B




Zone B Speed Road before



Zone B Speed Road after



Zone B Speed Road before



Zone B Speed Road after

--	--

**ZONE C**



Zone C Leaf River Church Road before



Zone C Leaf River Church Road after