



Photo No. IMG_3040; Taken on 07/22/15 at 12:18 hours by START-JW. Facing Down. Location of WG-SW-0007. Teal colored outfall PVC pipe noted downstream from sample location.



Photo No. IMG_3041; Taken on 07/22/15 at 12:19 hours by START-JW. Facing Down. Location of WG-SW-0007.



Photo No. IMG_3042; Taken on 07/22/15 at 12:19 hours by START-JW. Facing Down. Location of WG-SW-0007. Teal colored outfall PVC pipe noted downstream from sample location.



Photo No. IMG_3043; Taken on 07/22/15 at 12:20 hours by START-JW. Facing Down. START collecting WG-SW-0007.




Photo No. IMG_0523; Taken on 07/22/15 at 12:45 hours by START-BH. Facing N/A. Inside the teal outfall pipe at WG-SW-0007.



Photo No. IMG_3044; Taken on 07/22/15 at 13:05 hours by START-JW. Facing Down. Location of the sample WG-PW-0001.



Photo No. IMG_3046; Taken on 07/22/15 at 13:27 hours by START-JW. Facing Down. START setting up for collection of sample WG-PW-0001.



Photo No. IMG_3047; Taken on 07/22/15 at 13:29 hours by START-JW. Facing Down. Beginning to pump water at WG-PW-0001.



Photo No. IMG_3048; Taken on 07/22/15 at 13:32 hours by START-JW. Facing Down. START collecting WG-PW-0001.



Photo No. IMG_3049; Taken on 07/22/15 at 13:32 hours by START-JW. Facing Down. Closeup of START collecting WG-PW-0001.



Photo No. IMG_3050; Taken on 07/22/15 at 13:41 hours by START-JW. Facing Down. START collecting WG-PW-0001.



Photo No. IMG_3051; Taken on 07/22/15 at 13:50 hours by START-JW. Facing Down. YSI Meter face. Water quality measurements for sample WG-PW-0001.



Photo No. IMG_3052; Taken on 07/22/15 at 14:29 hours by START-JW. Facing Down. Set-up and location of sample WG-PW-0002 and duplicate WG-PW-0003.



Photo No. IMG_3053; Taken on 07/22/15 at 14:32 hours by START-JW. Facing Down. START collecting WG-PW-0002 and duplicate WG-PW-0003.



Photo No. IMG_3054; Taken on 07/22/15 at 14:33 hours by START-JW. Facing Down. START collecting WG-PW-0002 and duplicate WG-PW-0003.



Photo No. IMG_3055; Taken on 07/22/15 at 14:46 hours by START-JW. Facing Down. YSI Meter face. Water quality measurements for sample WG-PW-0002/0003.



Photo No. IMG_0527; Taken on 07/22/15 at 15:26 hours by START-BH. Facing Down. YSI Meter face. Water quality measurements in stream during sampling of WG-PW-0001.



Photo No. IMG_0528; Taken on 07/22/15 at 15:27 hours by START-BH. Facing Down. YSI Meter face. Water quality measurements in stream during sampling of WG-PW-0001.



Photo No. IMG_0529; Taken on 07/22/15 at 15:27 hours by START-BH. Facing Down. YSI Meter face. Water quality measurements in stream during sampling of WG-PW-0001.




Photo No. IMG_0525; Taken on 07/22/15 at 15:10 hours by START-BH. Facing N/A. Diagram on side of sump.



Photo No. IMG_0526; Taken on 07/22/15 at 15:10 hours by
START-BH. Facing N/A. Diagram on side of sump.