



Time: 7:00	Time: 12:00	Time: 3:45
Wind Speed: 4.6 mph	Wind Speed: 4.6 mph	Wind Speed: 6.9 mph
Wind direction: NE	Wind direction: E	Wind direction: ESE
Temp: 65 F	Temp: 72 F	Temp: 78 F
Humidity: 90 %	Humidity: 78 %	Humidity: 64 %
Pressure: 30.23 in.	Pressure: 30.22 in.	Pressure: 30.13 in.

Air Monitoring Station	TWA from 07:30-07:45	TWA from 12:00-12:15	TWA from 15:20-15:35	Total TWA for the day
Princeton S1	28.93 ug/m ³	24.87 ug/m ³	21.13 ug/m ³	29.75 ug/m ³
Princeton S2	31.4 ug/m ³	21.8 ug/m ³	17.8 ug/m ³	29.97 ug/m ³
Princeton S3	27.0 ug/m ³	22.07 ug/m ³	13.67 ug/m ³	23.2 ug/m ³
Princeton S4 (background)	30.33 ug/m ³	21.87 ug/m ³	14.2 ug/m ³	24.51 ug/m ³
Princeton S5	21.67 ug/m ³	13.6 ug/m ³	5.73 ug/m ³	14.75 ug/m ³

Comments: Excavation activities continue at the northwest portion of the site. S4's readings may be affected by traffic on Lawrence Drive. Wind direction primarily E, background data based on S4. Particulate air samples collected.

