



Time: 7:00	Time: 12:00	Time: 14:30
Wind Speed: 7 mph	Wind Speed: 11.5 mph	Wind Speed: 8 mph
Wind direction: N	Wind direction: NE	Wind direction: NNE
Temp: 47 F	Temp: 61 F	Temp: 66 F
Humidity: 83 %	Humidity: 60 %	Humidity: 48 %
Pressure: 30.18 in.	Pressure: 30.16 in.	Pressure: 30.09 in.

Air Monitoring Station	TWA from	TWA from	TWA from	Total TWA for the day
Princeton S1	13.53 ug/m ³	10.60 ug/m ³	10.67 ug/m ³	10.78 ug/m ³
Princeton S2	21.07 ug/m ³	11.67 ug/m ³	11.33 ug/m ³	10.15 ug/m ³
Princeton S3	11.07 ug/m ³	7.73 ug/m ³	5.80 ug/m ³	7.93 ug/m ³
Princeton S4	11.20 ug/m ³	6.73 ug/m ³	5.20 ug/m ³	7.43 ug/m ³
Princeton S5	7.07 ug/m ³	1.33 ug/m ³	1.00 ug/m ³	2.80 ug/m ³

Comments: Excavation activities continued on-site. Air monitoring stations were deployed today. S4's readings may be affected by traffic on Lawrence Drive. Wind direction primarily NE. Particulate air samples not collected.

