



Time: 7:00	Time: 12:00	Time: 14:30
Wind Speed: N/A	Wind Speed: 4 mph	Wind Speed: 7 mph
Wind direction: N/A	Wind direction: N	Wind direction: NW
Temp: 50 F	Temp: 68 F	Temp: 73 F
Humidity: 90 %	Humidity: 43 %	Humidity: 46 %
Pressure: 30.05 in.	Pressure: 30.03 in.	Pressure: 29.95 in.

Air Monitoring Station	TWA from	TWA from	TWA from	Total TWA for the day
Princeton S1	12.47 ug/m <sup>3</sup>	4.33 ug/m <sup>3</sup>	1.07 ug/m <sup>3</sup>	7.54 ug/m <sup>3</sup>
Princeton S2	14.07 ug/m <sup>3</sup>	1.47 ug/m <sup>3</sup>	9.80 ug/m <sup>3</sup>	7.60 ug/m <sup>3</sup>
Princeton S3 (background)	14.47 ug/m <sup>3</sup>	3.67 ug/m <sup>3</sup>	2.07 ug/m <sup>3</sup>	8.14 ug/m <sup>3</sup>
Princeton S4	12.47 ug/m <sup>3</sup>	3.00 ug/m <sup>3</sup>	1.60 ug/m <sup>3</sup>	5.38 ug/m <sup>3</sup>
Princeton S5	11.67 ug/m <sup>3</sup>	1.87 ug/m <sup>3</sup>	2.20 ug/m <sup>3</sup>	3.55 ug/m <sup>3</sup>

Comments: Excavation activities continued on-site. Air monitoring stations were deployed today. S4's readings may be affected by traffic on Lawrence Drive. Wind direction primarily N, background data based on S3. Particulate air samples not collected.

