




- Legend**
- KYDEP Total Metal/TCLP Sampling**
    - Sample Location (10/22/2014)
    - Sample Location (10/2/2014)
  - EPA/START Screening-Sampling**
    - XRF Readings Above LOD
    - XRF Readings Below LOD
    - EPA/START Waste Pile Sample Location (3/24/2015)
    - Surface Water Drainage Flow Direction
    - Drainage Pathway
    - Fence (section)
    - Estimated Location of Barbed-Wire Fencing/Property Line
    - Driveway/Gravel Road
    - Approximate Location of Dozer Pile
    - Paved Concrete Surface
    - Approximate Location of Arsenic Waste Site
    - Approximate Location of Former Barn
    - Structure
    - Approximate Parcel Boundary



**Notes:**  
 LOD - Level of Detection  
 TCLP - Toxicity Characteristic Leaching Procedure  
 XRF screening results in ppm



**FIGURE X**  
 XRF Screening and Sample Results  
 10/2/14, 10/22/14, 3/24/15

**TDD Name:** Wiley Property  
**TDD No.:** TT-02-002

**City:** Hartford    **County:** Ohio    **State:** Kentucky

**Tetra Tech**    **Date:** 9/24/2015  
**Analyst:** daie.vonbusch

