


Perimeter Air Sampling Results Summary
September 24, 2015
Princeton Recycles Site
Princeton, NJ



Sample Location	Benzo[a]pyrene	PCBs	Lead
Action Levels	0.1 ug/m ³	0.5 ug/m ³	0.15 ug/m ³
Princeton S1	ND (<0.20 ug/m ³)	ND (0.046 ug/m ³)	ND (0.047 ug/m ³)
Princeton S2	ND (<0.20 ug/m ³)	ND (0.046 ug/m ³)	ND (0.047 ug/m ³)
Princeton S3	ND (<0.20 ug/m ³)	ND (0.046 ug/m ³)	ND (0.048 ug/m ³)
Princeton S4	ND (<0.20 ug/m ³)	ND (0.046 ug/m ³)	ND (0.048 ug/m ³)
Princeton S5	ND (<0.20 ug/m ³)	ND (0.047 ug/m ³)	ND (0.048 ug/m ³)

ND = Non-detect

-- = Not Sampled

ug/m³ = micrograms per meter cubed

Comments: Excavation activities continue at the northwest portion of the site. Wind direction primarily NE, background data based on S3.