


Perimeter Air Sampling Results Summary  
October 15, 2015  
Princeton Recycles Site  
Princeton, NJ



Sample Location	Benzo[a]pyrene	PCBs	Lead
Action Levels	0.1 ug/m <sup>3</sup>	0.5 ug/m <sup>3</sup>	0.15 ug/m <sup>3</sup>
Princeton S1	ND (0.10 ug/m <sup>3</sup> )	ND (0.051 ug/m <sup>3</sup> )	0.072 ug/m <sup>3</sup>
Princeton S2	ND (0.098 ug/m <sup>3</sup> )	ND (0.046 ug/m <sup>3</sup> )	ND (0.048 ug/m <sup>3</sup> )
Princeton S3	ND (0.17 ug/m <sup>3</sup> )	ND (0.050 ug/m <sup>3</sup> )	ND (0.047 ug/m <sup>3</sup> )
Princeton S4	ND (0.19 ug/m <sup>3</sup> )	ND (0.053 ug/m <sup>3</sup> )	ND (0.051 ug/m <sup>3</sup> )
Princeton S5	ND (0.19 ug/m <sup>3</sup> )	ND (0.050 ug/m <sup>3</sup> )	ND (0.051 ug/m <sup>3</sup> )

ND = Non-detect

-- = Not Sampled

ug/m<sup>3</sup> = micrograms per meter cubed

Comments: Excavation activities continue at the northwest portion of the site. Wind direction primarily out of the NW, background data based on S4.