

## Rosebud Lift Station

---

### Photo Log

---

Description: Rosebud Creek near the lift station.

Category: Assessment

Latitude: 43.2375589

Date Taken: 4/20/2017

Longitude: -100.8576109

Tags: Safety Message



Description: View from the opposite side of Rosebud Creek from the discharge point showing the untreated water flowing over the riverbank and into Rosebud Creek.

Category: Assessment

Latitude: 43.2373866666667

Date Taken: 4/20/2017

Longitude: -100.857788333333

Tags: Admin Record



Description: Manhole overflowing untreated water due to pump failure at the lift station.

Category: Assessment

Latitude: 43.237305

Date Taken: 4/20/2017

Longitude: -100.857491666667

Tags: Admin Record



Description: Untreated water from an overflowing manhole.

Category: Assessment

Latitude: 43.2372333333333

Date Taken: 4/20/2017

Longitude: -100.857291666667

Tags: Admin Record, Current Situation



Description: Untreated water from the overflowing manhole running into the storm drain.

Category: Assessment

Latitude: 43.2372333333333

Date Taken: 4/20/2017

Longitude: -100.857278333333

Tags: Admin Record



## Rosebud Lift Station

---

### Photo Log

---

Description: Workers are moving untreated water from the lift station to a discharge point on Rosebud Creek so they can attach a temporary pump to the existing piping of the lift station.

Category: Removal

Latitude: 43.237295

Date Taken: 4/20/2017

Longitude: -100.857483333333

Tags:



Description: Untreated water discharged from the pipe outlet running down the side slope of the vegetated riverbank and into Rosebud Creek.

Category: Removal

Latitude: 43.2374033333333

Date Taken: 4/20/2017

Longitude: -100.857483333333

Tags:



Description: Manhole no longer overflowing sewage due to transfer pump rerouting untreated water to Rosebud Creek.

Category: Removal

Latitude: 43.2373166666667

Date Taken: 4/20/2017

Longitude: -100.857496666667

Tags:



Description: Temporary pump brought in by EPA to bypass the lift station.

Category: Removal

Latitude: 43.237426

Date Taken: 4/20/2017

Longitude: -100.857289

Tags:



## Rosebud Lift Station

---

### Photo Log

---

Description: Temporary bypass pump being installed.

Category: Removal

Latitude: 43.237426

Date Taken: 4/20/2017

Longitude: -100.857289

Tags: Resource Summary

---



Description: Temporary diesel pump hooked up to bypass the lift station.

Category: Removal

Latitude: 43.2373972222222

Date Taken: 4/20/2017

Longitude: -100.857308333333

Tags: Current Actions

---



Description: Piping tee that is transferring water from the wet well to the outlet pipe in the dry well which connects to the next lift station.

Category: Removal

Latitude: 43.2373972222222

Date Taken: 4/20/2017

Longitude: -100.857308333333

Tags: Planned Activities

---



Description: View inside the wet well showing the temporary pump influent pipe and the level float positions required to activate the pump.

Category: Removal

Latitude: 43.2374027777778

Date Taken: 4/20/2017

Longitude: -100.857308333333

Tags: Response Objectives

---



## Rosebud Lift Station

---

### Photo Log

---

Description: Temporary pump inlet transferring untreated water from the wet well to lift station outlet. The water level can be seen at the bottom of the well after pump shut down due to low water level.

Category: Removal

Latitude: 43.2374

Date Taken: 4/20/2017

Longitude: -100.8573

Tags:



Description: Temporary pump outlet connecting to the lift station outlet in the dry well. The valve for the lift station outlet can be seen as the red bar.

Category: Removal

Latitude: 43.23745

Date Taken: 4/20/2017

Longitude: -100.857247222222

Tags:

