


Legend

-  Site Boundary
-  Drum Pile
-  Western School
- Unlined Agricultural Ditch



PREPARED BY:
 Region 9, START
 Weston Solutions, Inc.
 2300 Clayton Road
 Suite 900
 Concord, CA 94520



PREPARED FOR:
 EPA Region 9
 Pacific
 Southwest



FIGURE 2
SITE LAYOUT
 2761 S. Fruit Avenue
 Fresno, Fresno County, CA

Legend

-  Site Boundary
-  Drum Pile
-  Unlined Agricultural Ditch



PREPARED BY:
Region 9, START
Weston Solutions, Inc.
2300 Clayton Road
Suite 900
Concord, CA 94520



PREPARED FOR:
EPA Region 9
Pacific
Southwest



FIGURE 3
DRUM PILES MAP
2761 S. Fruit Avenue
Fresno, Fresno County, CA

| | | |
|---|---|---|
| Project Name: Fresno Drum Assessment ER | Site Location: 2761 Fruit Avenue, Fresno, Fresno County, California | TDD No.: 0002/1302-T2-R9-19-04-0002 |
|---|---|---|

| | |
|-----------------------|-------------------------|
| Photo No. 1 | Date: 3/14/19 |
|-----------------------|-------------------------|

Direction:
NW

Description:
View of Pile 1, single level arrangement with approximately 177 drums.



| | |
|-----------------------|---------------------------|
| Photo No. 2 | Date: 3/14/2019 |
|-----------------------|---------------------------|

Direction:
SE

Description:
View of Pile 2, double level arrangement with approximately 415 drums.



| | | |
|---|---|---|
| Project Name: Fresno Drum Assessment ER | Site Location: 2761 Fruit Avenue, Fresno, Fresno County, California | TDD No.: 0002/1302-T2-R9-19-04-0002 |
|---|---|---|

| | |
|-----------------------|---------------------------|
| Photo No. 3 | Date: 3/14/2019 |
|-----------------------|---------------------------|

Direction:
W

Description:
View of Group 1 consisting of blue metal drums with Chevron markings.



| | |
|-----------------------|---------------------------|
| Photo No. 4 | Date: 3/14/2019 |
|-----------------------|---------------------------|

Direction:
E

Description:
View of Group 2 consisting of red metal drums with Mobile 1 markings.



Project Name:
Fresno Drum Assessment ER

Site Location:
2761 Fruit Avenue, Fresno, Fresno County,
California

TDD No.:
0002/1302-T2-R9-19-04-0002

Photo No.
5 **Date:**
3/14/2019

Direction:
NE

Description:
View of Group 4
consisting of yellow metal
drums with Chevron
markings.



Photo No.
6 **Date:**
3/14/2019

Direction:
NW

Description:
View of Group 7
consisting of white metal
drums with no markings
and two sample
containers, and Group 8
consisting of black metal
drums with no markings.



| | | | |
|--|----------------------|---|-----------------------------|
| Facility Name & Location: Fresno S Fruit Ave Drum Site, Fresno CA | | Photographer: JOHNSTONE | Camera: iPhone 6s |
| Dates Photographs Were Taken: 14 March 2019 | |  | |
| Photo No. 1 | Time: 1110 | | |
| Direction Photo Taken: South | | | |
| Photo Description: Drum Pile #1 showing soil staining from leaking drums | | | |