



## Photographic Documentation

**Client:** EPA

**Site Name:** Julio Properties – RS

**Location:** Ripley, Michigan

**Prepared by:** Jeffrey S. Binkley

**TO-TO Line Item No.:** F0069-0002A1076r

**Dates:** 10/24 & 11/6/19 and 9/14 & 9/24/18

### Photograph No. 1

**Date:** 11/6/19

**Description:** View looking east/southeast of near trail debris in Priority Area 1 of the Julio Salvage property.



### Photograph No. 2

**Date:** 11/6/19

**Description:** View looking southeast of near trail debris in Priority Area 1 of the Julio Salvage property.





## Photographic Documentation

**Client:** EPA

**Site Name:** Julio Properties – RS

**Location:** Ripley, Michigan

**Prepared by:** Jeffrey S. Binkley

**TO-TO Line Item No.:** F0069-0002A1076r

**Dates:** 10/24 & 11/6/19 and 9/14 & 9/24/18

### Photograph No. 3

**Date:** 11/6/19

**Description:** View looking southeast of near trail abandoned containers in Priority Area 7 of the Julio Salvage property.



### Photograph No. 4

**Date:** 11/6/19

**Description:** View looking west of near trail salvage materials in Priority Area 7 of the Julio Salvage property.







## Photographic Documentation

**Client:** EPA

**Site Name:** Julio Properties – RS

**Location:** Ripley, Michigan

**Prepared by:** Jeffrey S. Binkley

**TO-TO Line Item No.:** F0069-0002A1076r

**Dates:** 10/24 & 11/6/19 and 9/14 & 9/24/18

### Photograph No. 5

**Date:** 9/14/18

**Description:** View looking north of compressed gas cylinder near trail in Priority Area 7 of the Julio Salvage property.



### Photograph No. 6

**Date:** 9/24/18

**Description:** View looking southwest of near trail abandoned containers in Priority Area 2 of the Julio Salvage property.







## Photographic Documentation

**Client:** EPA

**Site Name:** Julio Properties – RS

**Location:** Ripley, Michigan

**Prepared by:** Jeffrey S. Binkley

**TO-TO Line Item No.:** F0069-0002A1076r

**Dates:** 10/24 & 11/6/19 and 9/14 & 9/24/18

### Photograph No. 7

**Date:** 9/24/18

**Description:** View looking southwest of near trail abandoned containers in Priority Area 2 of the Julio Salvage property.



### Photograph No. 8

**Date:** 9/24/18

**Description:** View looking south of near trail abandoned container in Priority Area 2 of the Julio Salvage property.

